## FIRST AUTOWORKS

Date: 25/07/2024

Reference:

SMV 2780Z

Make:

Toyota Prius

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SMV 2780Z

CHASSIS NO.: JTDZS3EUX0J060411

ENGINE NO.: 2ZR2H36024

Name of insured .: Asiah Binte Omar Date of accident.: 23/07/2024

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

**Parts** 

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER Relief	380.00
2	2	FRT BUMPER BUMPER BRACKET ATT PH Counter	120.00 60
3	1	RHF FENDER Ded	480.00
4	1	RHF LED FOG LAMP CL	180.00 🗸
5	1	RH WING MIRROR	580.00 t.

Parts Total: 1,740.00 Less25%: 435.00 Total:

1,305.00

Labour		
No.	<u>Labour Description</u>	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair /replacement parts.	1000,00 40

1200.00 600 2 Carry out spray painting on accident affected area. (Frt Bumper) To disconnect wire harness of electrical component to facilitate 3 repairs, reconnect and check electrical function after repair

> Labour Total: 2.280.00

Other

No.		Other Description	Price (SGD)
1	10	FRT BUMPER CLIP	40.00
	1	V - V	

Other Total: 40.00

\$3,625.00

\$290.00

\$3.915.00

Total:

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Gst (8%): **GRAND TOTAL:** 

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU

WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Adria (5) 24.