

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

29 JULY 2024

Estimate No. : b1 70659	Page No. : 1 of 5
Date Estimated : 29/07/2024	
Prepared By : Yap Mee Key	

- ESTIMATE REPAIR FOR - Petrina Teoh Pei Zhen (Zhang Peizhe) 35 Jalan Sindor Singapore 808390	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX84B	WBA1L72050V491649	18/11/2015	220i-C	105606

DESCRIPTION	VALUE
To replace front bumper, front left fender and attachments.	1,700.00
To respray front bumper, front left fender and affected areas.	1,923.00
To check electrical wiring system and lighting at the frontsection for proper function.	177.00
To replace left headlamp.	481.00
Sundries.	80/? 150.00
To carry out body cavity preservation. (Per panel).	118.00

Total Labour 1: 4,549.00

DESCRIPTION	QTY	PRIC	VALUE
STICK ON LABEL (NO PDC) <i>7 Xnn</i>	1	0.25	0.25
FRT LH FENDER <i>repair</i>	1	652.90	652.90
FRT LH SIDE PANEL BRACKET 2 <i>Xnn</i>	1	44.15	44.15
FRT LH SIDE PANEL BRACKET 1 <i>Xnn</i>	1	44.15	44.15
Set of mount <i>Xnn</i>	1	67.70	67.70
FRT LH SIDE PANEL SUPPORT <i>3 new</i>	1	14.35	14.35
FRT BUMPER LH INSERT <i>2 new</i>	1	57.55	57.55
FRT BUMPER PANEL PRIMED (M SRA) <i>See</i>	1	1,207.45	1,207.45
SET OF DUMMY TRIMS (GEN 5 X) <i>See</i>	1	58.10	58.10
GROMMET <i>See</i>	2	0.80	1.60
PLAQUE 82MM <i>See</i>	1	76.55	76.55
LH BI-XENON HEADLIGHT <i>See</i>	1	1,969.55	1,969.55
DECOUPLING RING PDC TORQUE CONVERTE <i>Xnn</i>	6	5.65	33.90

Total Parts : 4,228.20



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 70659
Date Estimated : 29/07/2024
Prepared By : Yap Mee Key

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX84B	WBA1L72050V491649	18/11/2015	220i-C	105606

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pass
4p 9001w6x
4 days
07/08/24
By b4 part



Labour 1	:	4,549.00
Parts	:	4,228.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	789.95

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 70659
Date Estimated : 29/07/2024
Prepared By : Yap Mee Key

Page No. :

- ESTIMATE REPAIR FOR -
Petrina Teh Pei Zhen (Zhang Peizhen)
35 Jalan Sindor

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 808390

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SKX84B	WBA1L72050V491649	18/11/2015	220i-C	105606

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT BUMPER RH INSERT <i>cm</i>	57.55	1.00	0.00	57.55
# LH TELESCOPIC NOZZLE <i>cm</i>	175.25	1.00	0.00	175.25

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	232.80
Total Labour & Parts (before GST) :	232.80

Performance Motors Limited.
Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

A Sime Darby Motors Company