

KIEN CHEONG AUTOMOTIVE

BLK 9 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-26 SINGAPORE 575644

H/P : 8125 9406 FAX : 64550902

The Motor Claims Dept.
Liberty Insurance
(LKK)

Not Notified
11 Sep 84650h
Heavy After Paint

DATE : 29/7/2024
VEHICLE NO : SMJ 2099 X
MAKE/MODEL : ~~TOYOTA~~ GRACE
ACC DATE : 26/7/2024

ESTIMATE

6- days

S/N	PC	Nett ITEMS:	Page 1	AMOUNT SS
			<i>951.60</i>	<i>1,327.40</i> ✓
1	1	Rear boot lid		<i>Sm</i> 270.30 X
2	1	Rear boot outer chrome		<i>Sm</i> 1,406.90 X
3	1	Rear boot spoiler		<i>CM/LW</i> 713.80 ✓
4	2	Rear boot lamp @\$356.90 <i>e310</i>		<i>na</i> 58.20 ✓
5	1	Rear boot logo		<i>na</i> 75.60 ✓
6	1	Rear boot emblem "GRACE" <i>48</i>		<i>na</i> 88.30 ✓
7	1	Rear boot emblem "Hybrid" <i>60</i>		<i>na</i> 109.60 ✓
8	1	Rear boot Weatherstrip		<i>CM/LW</i> 921.00 ✓
9	2	Rear tailamp @\$460.50 <i>C381-w</i>		<i>na</i> 1,200.70 ✓
10	1	Rear bumper <i>585-60</i>		<i>na</i> 119.90 X
11	1	Rear bumper inner sponge		<i>na</i> 65.90 ✓
12	1	Rear bumper lower grille		<i>na</i> 83.60 X
13	2	Rear bumper reflector cover @\$41.80		<i>na</i> 160.60 X
14	2	Rear bumper reflector @\$80.30		<i>na</i> 67.20 LP
15	2	Rear bumper side retainers @\$33.60		<i>na</i> 1,055.30 X
16	1	Rear floor panel		<i>na</i> 913.70 ✓
17	1	Rear end panel <i>415</i>		<i>na</i> 118.70 X
18	1	Rear end panel top garnish		<i>na</i> 489.00 X
19	1	Spare tyre top board	<i>dis</i>	<i>na</i> 612.00 X
20	2	Rear fender inner trim @\$306.00		<i>na</i> 935.60 X
21	1	Rear RH fender		10,793.30
				(2,698.33)
				8,094.97

Special Items :

- | | | |
|---|---|------------------------------|
| 1 | 1 | Rear bumper clip (1 set) |
| 2 | 1 | End panel sealant |
| 3 | 1 | Reverse sensor |
| 4 | 1 | Rear fender inner trim clips |
| 5 | 1 | Spare tyre panel sealant |
| 6 | 1 | Rear number plate |
| 7 | 1 | Rear reverse camera |
| 8 | 1 | Rear boot lid sticker |

na 100.00 *405n*
na 100.00 *305n*
CM 300.00 *2005n*
na 100.00 X
na 100.00 X
na 65.00 X
na 400.00 X
na 100.00 *205n*
1,265.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KIEN CHEONG AUTOMOTIVE

BLK 9 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-26 SINGAPORE 575644

H/P : 8125 9406 FAX : 64550902

The Motor Claims Dept.

Liberty Insurance

(LKK)

DATE : 29/7/2024

VEHICLE NO : SMJ 2099 X


MAKE/MODEL : TOYOTA GRACE

ACC DATE : 26/7/2024

ESTIMATE

S/N	PC	Labour Charge	Page 2	AMOUNT S\$	
1		To check up rear electrical wiring		60.00	20/-
2		To transfer boot lid machansim		100.00	50/-
3		To replace reverse sensor		100.00	50/-
4		To remove rear exhaust to faciliate repair	nn	150.00	50/-
5		To remove rear upholstery to faciliate repair		150.00	80/-
6		To apply anti rust		100.00	60/-
7		To replace reverse camera		100.00	40/-
8		To putty and respray painting affected area		1,400.00	1200/-
9		To cut and weld end panel, spare tyre panel and repair rear fender		1,600.00	900/-
				3,760.00	
Total Repair Cost				13,119.97	

(S/D : Thirteen Thousand One Hundred Nineteen and cents Ninety-seven only.)



KIEN CHEONG AUTOMOTIVE

BLK 9 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-26 SINGAPORE 575644

H/P : 8125 9406 FAX : 64550902

The Motor Claims Dept.
Liberty Insurance
(LKK)

DATE : 29/7/2024
VEHICLE NO : SMJ 2099 X
MAKE/MODEL : TOYOTA GRACE
ACC DATE : 26/7/2024

SUPPLEMENTARY ESTIMATE

S/N	PC	Netts Items	AMOUNT SS
1	1	Rear boot lock	254.95 ✓

208

(S/DLS : Two Hundred Fifty-four and cents Ninety-five only.)

