

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 29.07.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMF3169S**
MODEL : **MITSUBISHI OUTLANDER**
DATE OF ACCIDENT : 19.07.2024
TIME OF ACCIDENT : 10:00 HOURS

Veron.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Pished</i>	1	\$ 863.00	\$ 863.00
2	FRONT BUMPER LOWER <i>Delnd</i>	1	\$ 517.00	\$ 517.00
3	FRONT BUMPER LOWER COVER <i>new</i>	1	\$ 220.00	\$ 220.00
4	FRONT BUMPER TOP BEAM <i>Beated</i>	1	\$ 340.00	\$ 340.00
5	FRONT BUMPER SIDE RETAINER <i>2 of</i>	2	\$ 48.00	\$ 96.00
6	FRONT BUMPER SIDE BRACKET <i>2 of</i>	2	\$ 18.00	\$ 36.00
7	FRONT BUMPER FOG LAMP <i>2 of LH and</i>	2	\$ 350.00	\$ 700.00
8	FRONT BUMPER FOG LAMP WIREHARNES <i>at</i>	1	\$ 286.00	\$ 286.00
9	FRONT BUMPER FOG LAMP COVER <i>2 of LH and</i>	2	\$ 112.00	\$ 224.00
10	FRONT BUMPER CENTER GRANISH <i>cut</i>	1	\$ 138.00	\$ 138.00
11	FRONT BUMPER CENTER GRILLE BASE <i>could</i>	1	\$ 550.00	\$ 550.00
12	FRONT BUMPER CENTER GRILLE LOGO <i>de</i>	1	\$ 98.00	\$ 98.00
13	FRONT BUMPER CENTER GRILLE BRACKET (SIDE) <i>2 of</i>	2	\$ 18.00	\$ 36.00
14	FRONT BUMPER CENTER GRILLE BRACKET (CENTER) <i>1 of</i>	1	\$ 58.00	\$ 58.00
15	FRONT BUMPER SIDE CHROME MOULDING (UPPER) <i>2 of LH and</i>	2	\$ 220.00	\$ 440.00
16	FRONT BUMPER SIDE CHROME MOULDING (LOWER) <i>2 of LH and</i>	2	\$ 116.00	\$ 232.00
17	FRONT BUMPER SIDE ARCH GARNISH <i>new 2 of</i>	2	\$ 162.00	\$ 324.00
18	FRONT BUMPER BOTTOM COVER <i>for</i>	1	\$ 485.00	\$ 485.00
19	FRONT BUMPER REINFORCEMENT <i>Beated</i>	1	\$ 513.00	\$ 513.00
20	FRONT BUMPER LOWER BEAM <i>new DD</i>	1	\$ 138.00	\$ 138.00
21	FRONT SUPPORT TOP GRANISH <i>new</i>	1	\$ 168.00	\$ 168.00

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMF3169S**
 MODEL : MITSUBISHI OUTLANDER
 DATE OF ACCIDENT : 19.07.2024
 TIME OF ACCIDENT : 10:00 HOURS

22	FRONT FENDER INNER COWRING <i>et new</i>	(2)	\$ 358.00	\$ 716.00	+
23	HEADLAMPS <i>et LH cracked, RH int</i>	(2)	\$ 1,984.00	\$ 3,968.00	✓
24	HORN <i>et 3 new</i>	(2)	\$ 65.00	\$ 130.00	+
25	AIRCON CONDENSOR	1	\$ 1,038.00	\$ 1,038.00	+
26	AIR CON CONDENSER SIDE GARNISH <i>et new</i>	(2)	\$ 85.00	\$ 170.00	+
27	OUTSIDE TEMPERATURE ENSOR <i>new</i>	1	\$ 138.00	\$ 138.00	+

8628
7765.20

TOTAL PRICE	\$ 12,622.00
LESS 10%	\$ 1,262.20
SUB TOTAL PRICE	\$ 11,359.80 ✓

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00	-
2	FRONT BUMPER CLIP (SET) <i>m</i>	1	\$ 50.00	\$ 50.00	30
3	FRONT BUMPER BOTTOM COVER TOP GARNISH CLIP (SET) <i>m</i>	1	\$ 30.00	\$ 30.00	✓
4	FRONT BUMPER LOWER GRILLE CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
5	FRONT FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
6	FRONT GRILLE CLIP (SET) <i>m</i>	1	\$ 30.00	\$ 30.00	✓
7	AIR CON CONDENSER SIDE GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
8	AIR DUCT CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
9	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+

140 TOTAL \$ 350.00 ✓

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	300
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	200
3	TUFF COAT	\$ 250.00	+
4	WIRING CHECK	\$ 250.00	30

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMF3169S**
 MODEL : MITSUBISHI OUTLANDER
 DATE OF ACCIDENT : 19.07.2024
 TIME OF ACCIDENT : 10:00 HOURS

5	REFOCUS HEADLAMP BEAM	\$ 60.00	X
6	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	X
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

530

TOTAL \$3,990.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,709.80 ✓
 TOTAL LABOUR COST : \$ 3,990.00 ✓
 TOTAL REPAIR COST : \$ 15,699.80

Adrian L
 1/5 30/07/24
 03 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

total 8435.20
1/5 : 6750 ✓

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: