



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNN 8660C

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOOTLID	BENT	\$1,725.60	\$1,601.80
1	REAR BUMPER	BENT	\$480.20	\$480.20
1	REAR BUMPER EXTENTION -L/H	BUCKLED	\$180.20	\$180.20
2	REAR REVERSE SENSOR@240	DENTED (1PC ONLY)	\$480.00	\$240.00
1	REAR BUMPER REFLECTOR -R/H	CUT	\$59.90	\$59.90
1	REAR END PANEL -INNER	BENT	\$566.80	\$566.80
1	REAR BUMPER RETAINER -L/H	DISTORTED	\$103.20	\$103.20
1	REAR END PANEL -LOWER	BENT	\$905.60	\$801.40
	LESS 25.00% DISCOUNT		(\$1,125.38)	(\$1,008.37)
			\$3,376.12	\$3,025.13

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	SPRAY PAINTING		\$700.00	\$650.00
	TO REPLACE ABOVE PARTS		\$800.00	\$700.00
	TO ANTI RUST		\$100.00	\$60.00
	TO CHECK WIRING		\$40.00	\$20.00
	TO REINSTATE WINDSCREEN		\$150.00	\$120.00
	TO TRANSFER BOOTLID ACCESSORIES		\$80.00	\$60.00
			\$1,870.00	\$1,610.00

GRAND TOTAL	\$5,246.12	\$4,635.13
--------------------	-------------------	-------------------

RECOMMENDED COST OF REPAIRS		\$4,635.13
------------------------------------	--	-------------------

Report Ref No: CS/AGI24070467/Kvp3m4

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.