

ASS. REC. BY:

REF:

AG21

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ RC

of _____ 9287

Insured: _____ 2226

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1-B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNV 8660C Yr Regn: 12, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A) Wagon

Make: Toy Pienta c.c. 1490

Colour: M. Beige A/C: Insured / Std / NI / NA

Sp. Reading: 6187 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MxPL10 1084080

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / SRIm / STD A/Rim or

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 29/7/24

D.O.I. 29/7/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Kha n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 GIA & En not ready

16/8 84635.13 Cahn

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

RC AUTO

Not Withheld
Recovery B4 paint

6 days

4635.13

Date : 05.08.2024

Quantity	Description/Particular	Unit Price	Amount	
1 PC	REAR BOOLTID 160/-80	Ry	1725	60
1 PC	REAR BUMPER	Rn	480	20
1 PC	REAR BUMPER EXTENTION -L/H	Bu	180	20
2 PCS	REAR REVERSE SENSOR@240	Ncl	480	00
1 PC	REAR BUMPE REFLECTOR-R/H	Cm	59	90
1 PC	REAR END PANEL -INNER	Ry	566	80
1 PC	REAR BUMPER RETAINER -L/H	D's	103	20
1 PC	REAR END PANEL -LOWER 80/-40	Rn	905	60
	TOTAL		4500	90
	LESS 25		3375	67
	SPRAY PAINTING		700	00
	TO REPLACE ABOVE PARTS		800	00
	TO ANTI RUST		100	00
	TO CHECK WIRING		40	00
	TO REINSTATE WINDSCREEN		150	00
	TO TRANSFER BOOTLID ACCESSORIES		80	00
	LKK Auto Consultants hence notify the Repairer of the following: a To resurvey before/after spray painting		5245	67

Received the above goods in good order and condition

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: _____

Received by

E. & O. E.

Authorized Signature