



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24070470/Anh3
75 BRAS BASAH ROAD	Date:	16/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FU 6508G	Veh. Inspected	SLW 811M
Policy No.	-	Coverage	0
Claim No.	MT/1287086-002	Excess	\$0.00
Assign From	LIM SERENE	Assign Date	30/07/2024

2. Vehicle Details

Make & Model	TOYOTA SIENTA	C.C	1496
Engine No.	2NR8612316	Year of Reg.	21/09/2016
Chassis No.	NSP1707030915	Colour	RED
Odometer	321007 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/55R16	YOKOHAMA	6
L/H Front Tyre	185/55R16	YOKOHAMA	6
R/H Rear Tyre	185/55R16	YOKOHAMA	6
L/H Rear Tyre	185/55R16	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/07/2024	Inspection Date	30/07/2024 (18:44)
Survey held at	N-51 AUTOMOTIVE PTE LTD - 2 KAKI BUKIT AVE 2 #01-17/18 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a.	Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.	
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	

5b.	Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days	