



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

NG ENG HWA
BLK 511 CHO A CHU KANG ST 51 #07-245
SINGAPORE 680511

Contact : 91918895

TP NC

Hui Rong

TAX INVOICE

Repair Code : CLM18313

Date in : 19/07/2024

Vehicle Num. : SLW811M

Model : TOYOTA SIENTA 1.5G A

Chassis/Eng# : NSP1707030915/2NR8612316

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Repair</i>	1	511.60	511.60
FRONT BUMPER CENTER GRILLE <i>new</i>	1	1182.90	1,182.90
FRONT BUMPER FOGLAMP GARNISH RH <i>lit</i>	1	180.40	180.40
FRONT BUMPER FOGLAMP RH <i>new</i>	1	463.70	463.70
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	65.60	131.20
FRONT RH HEADLAMP <i>lit</i>	1	4859.90	4,859.90
Subtotal before discount			7,329.70
Percentage discount 25%			1,832.43
Sub-total 1			5,497.28
FRONT BUMPER CLIPS - SET <i>new</i>	1	80.00	80.00
Subtotal before discount			80.00
Percentage discount 0%			0.00
Sub-total 2			80.00
Parts-total			5,577.28

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

960.00

Parts & Labour Total

6,537.28

LKK Auto Consultants hence not the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Complementary item(s) must be resurveyed and is subject to final approval by LKK Auto Consultants

Acknowledged by Repairer:

Signature:

Date:

480 30 80.00
200 400.00
250 400.00
+ 80.00

total 3614.55 Admin L
2.9K H/S 2.9K 1/5 30/07/24
02 R/p

*** This is a computer-generated document which requires no signature.***