

ESTIMATE OF REPAIR

Hui King
JP INC

Veh# SNN2463U

Model: HONDA CROSS ROAD

Accident Date : 26/7/2024

8/7/2008 7/7/2028

Location : PIE TOWARDS TUAS

3P: GBJ9044M (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Distorted</i>	996.00	✓	
2	10 pcs	Rear bumper clips <i>new</i>		40.00 30	
3	1 pc	Rear bumper o/s & n/s top garnish <i>RH missing</i>	796.00	398	
4	1 pc	Rear bumper n/s tow cover <i>Missing</i>	50.00	✓	
5	2 pcs	Rear bumper o/s & n/s retainer <i>cracked</i>	343.80	170	
6	2 pcs	Rear bumper o/s & n/s bumper reflector <i>RH cracked</i>	256.20	128.10	
7	1 pc	Rear tail gate <i>Distorted</i>	1480.00	1248	
8	1 pc	Rear tail gate lower garnish <i>Delint</i>	610.20	✓	
9	1 pc	Rear tail gate weatherstrip <i>cut</i>	320.00	✓	
10	1 pc	Rear tail gate H emblem <i>new</i>	70.20	✓	
11	1 pc	Rear tail gate cross road emblem <i>new</i>	67.00	✓	
12	2 pcs	Rear tail gate hinges <i>new</i>	296.00	x	
13	1 pc	Rear tail gate lock <i>changed</i>	206.00	✓	
14	1 pc	Rear tail gate lock catch <i>new</i>	70.00	+	
15	1 pc	Rear tail gate lock handle (Outer) <i>new</i>	287.00	x	
16	1 pc	Rear tail gate inner trim <i>Delint</i>	490.00	✓	
17	12 pcs	Rear tail gate inner trim clips <i>new</i>	144.00	30	
18	2 pcs	Rear o/s & n/s tail lamp <i>cracked</i>	1360.00	870	
19	1 pc	Rear tail gate end panel <i>Delint</i>	678.20	✓	
20	1 pc	Rear tail gate end panel inner trim <i>Delint</i>	220.00	✓	
21	5 pcs	Rear tail gate end panel inner trim clips <i>new</i>	60.00	20	
22	1 pc	Rear enforcement <i>new</i>	235.60	x	
23	1 pc	Rear wiper motor <i>changed</i>	310.50	✓	
24	1 pc	Rear windscreen sealant <i>new</i>		80.00 40	
25	1 pc	Rear windscreen inner seal <i>new</i>		60.00 30	
26	1 pc	Rear windscreen solar film <i>new</i>		60.00 200	
27	1 pc	Rear windscreen <i>Shattered</i>	800.00	✓	
28	1 pc	Rear reverse camera <i>changed</i>		280.00	✓
29	1 pc	Rear exhaust muffler <i>new</i>	930.40	+	
30	2 pcs	Rear exhaust muffler mounting <i>new</i>	70.00	+	
31	1 pc	Rear reg. no. plate <i>cracked</i>		45.00 30	
32	1 pc	Rear reg. no. plate bracket <i>Delint</i>		29.00	✓
33	2 pcs	Rear reg. no. plate lamp <i>new</i>	206.00	x	
34	2 pcs	Rear reverse sensor <i>changed</i>		280.00 200	
35	1 pc	Front bumper <i>Delint</i>	1096.70	✓	
36	2 pcs	Front bumper o/s & n/s garnish <i>new</i>	734.20	x	
37	10 pcs	Front bumper clips <i>new</i>		30.00	✓

Rear RH inner side trim \$68 ✓

ut

✓38	1 pc	Front bumper insulator <i>new</i>	394.20	394.20	
✓39	1 pc	Front bumper enforcement <i>Dental</i>	586.70	586.70	
✓40	2 pcs	Front bumper o/s & n/s retainer <i>new</i>	386.70	386.70	
✓41	1 pc	Front grille <i>new</i>	436.70	436.70	
42	1 pc	Front grille emblem <i>new</i>	71.70	71.70	
43	6 pcs	Front grille clips <i>new</i>		18.00	
44	1 pc	Front grille seal <i>new</i>	206.90	206.90	
45	2 pcs	Front o/s & n/s head lamp <i>RH Could</i>	1896.80	1896.80	
46	1 pc	Front reg. no. plate <i>ct</i>		45.00	
47	1 pc	Front reg. no. plate bracket <i>new</i>		29.00	
Rear Fender inner trim RH & LH \$1480.2			Sub Total:	17,173.70	996.00 0.00
Rear End part trim top board \$175.2 <i>new</i>				20%	0% 10%
Front RH head lamp bracket \$95.1			After Less %:	13738.96	996.00 0.00
Labour <i>Refined Could</i>					
1		To dismantle rear portion, straighten & welding.	1400.00	1400.00	
2		To spray painting.	1200.00	1200.00	
3		To remove & replace rear reverse sensor.	80.00	80.00	
4		To remove & replace rear windscreen.	140.00	140.00	
5		To remove & replace rear tail gate. <i>R.H.ing</i>	100.00	100.00	
6		To check wiring.	50.00	50.00	
7		To re seal anti rust.	80.00	80.00	
Sub Total:				3,050.00	
Total:				17784.96	
After Less 20%:				14227.97	

11108.80
8887.04

SN: 917

2240

Chan

Chan San Choon
Director
DipEng. AAE MIMI,MSAE(Aust)



AL 8778 1999
24 hr accident call



Admin
1/s. 30/07/24.

09 Days.

Label: 1204404

2/s 9.61C ✓

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: