

Not Authorised
11 Aug & 320dp

AAD2407- III

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5301M

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

3 JUL 2024

SHC5301M

JTDCB3FU903091198

200303878K

TOYOTA

PRIUS GEN 4

28/7/2024

GBH9087A/ECICS

14/7/2020

	PART
1	COVER, FRONT BUMPER
1	ABSORBER, FRONT BUMPER ENERGY
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER
1	SUPPORT, FRONT BUMPER SIDE, RH
1	MOULDING, FRONT BUMPER SIDE, RH
1	COVER, FRONT BUMPER HOLE, RH
1	GRILLE SUB-ASSY, RADIATOR
1	GRILLE, RADIATOR, LOWER NO.1
1	JAR ASSY, WINDSHIELD WASHER
1	WHEEL, DISC
1	FENDER SUB-ASSY, FRONT RH
1	LINER, FRONT FENDER, RH
1	EMBLEM, SIDE PANEL, RH
1	UNIT ASSY, HEADLAMP, RH

	LIST	
\$	Bulldo	653.31 ✓
\$	R	100.91 X
\$	R	902.16 X
\$	Di's	100.49 ✓
\$	W	120.86 ✓
\$	MRI	38.22 ✓
\$	Sm	532.88 X
\$	Sm	224.70 X
\$	R	276.15 X
\$	Sm	2,554.70 X
\$	R	1,236.69 X
\$	Sm	255.36 X
\$	W	68.88 ✓
\$	mgem	3,325.56 ✓
TOTAL	\$	10,390.87
25%	\$	2,597.72
	\$	7,793.15

Special Nett

1	FRT BUMPER CLIP
1	FENDER LINER CLIP
1	FRT BUMPER SIDE RETAINER CLIP

\$	W	65.00 Gasa
\$	W	65.00 X
\$	W	65.00 X
TOTAL	\$	195.00

TOTAL PARTS \$ 7,988.15

LABOUR

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5301M**AAD2407-**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 250.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	<i>4401</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	<i>2501</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
TOTAL	\$	4,990.00	
Over All Total	\$	12,978.15	

(PART-BY-PART) Repair Days~~**07 Days**~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: