

Not Authised
L1 Rep & 1050p

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHC5262S

AAD2407-106

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHC5262S

JTDKB3FU103091177

200303878K

TOYOTA

PRIUS GEN 4

25/7/2024

SK 2949A / III

30/6/2020

31 JUL 2024

PART	LIST
1 COVER, REAR BUMPER	\$ 612.68 ✓
1 GUARD, REAR BUMPER, CENTER	\$ 472.19 ✓
1 REFLECTOR ASSY, REFLEX, RH	\$ 49.25 X
1 SEAL, REAR BUMPER SIDE, RH	\$ 149.21 X
1 REAR BUMPER SIDE RETAINER RH	\$ 167.48 X
1 PANEL SUB-ASSY, QUARTER, RH	\$ 1,099.46 X
1 LINER, REAR WHEEL HOUSE, RH	\$ 176.09 X
1 COVER, FLOOR UNDER, RH	\$ 220.50 X
1 COVER, FLOOR UNDER, LH	\$ 304.92 X
1 COVER, REAR FLOOR	\$ 290.43 X
1 COVER, DECK TRIM, REAR	\$ 159.39 X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$ 824.46 X
1 LENS & BODY, REAR COMBINATION LAMP, RH	\$ 428.19 X
1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$ 329.49 X
1 COVER, REAR COMBINATION LAMP, RH	\$ 88.41 X
TOTAL	\$ 5,372.15
25%	\$ 1,343.04
	\$ 4,029.11

SPECIAL NETT	
1SET PARKING AID	\$ 700.00 X
1 REAR BUMPER CLIP	\$ 65.00 6052
1 END PANEL INNER TRIM CLIP	\$ 60.00 X
1 REAR BUMPER PROTECTOR	\$ 180.00 X
2 WINDSCREEN SEALANT	\$ 150.00 X
1 WINDSCREEN MOULDING	\$ 200.00 X
1 WINDSCREEN INNER SPONGE SEAL	\$ 130.00 X
TOTAL	\$ 1,485.00
TOTAL PARTS	\$ 5,514.11

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHC5262S

AAD2407-

LABOUR

To rust-proofing of the affected areas.	\$	<i>nn</i> 600.00	X
Putty and spray painting of the affected portion.	\$	1,200.00	<i>2201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	<i>2001</i>
To transfer of tailgate fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>~</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>~</i> 380.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	<i>~</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>
To check steering geometry and computer wheel alignment	\$	<i>~</i> 220.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>~</i> 170.00	X

TOTAL \$ 5,250.00**OVERALL TOTAL \$ 10,764.11**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 days