

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**SHC5262S****AAD2407-**

Vehicle No.:	SHC5262S
Chassis No.:	JTDKB3FU103091177
Co UEN.:	200303878K
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS GEN 4
Date of Accident:	25/7/2024
Third Party Insurer:	
Date of Registration:	30/6/2020

PART		LIST	
1	COVER, REAR BUMPER	\$	612.68
1	GUARD, REAR BUMPER, CENTER	\$	472.19
1	REFLECTOR ASSY, REFLEX, RH	\$	49.25
1	SEAL, REAR BUMPER SIDE, RH	\$	149.21
1	REAR BUMPER SIDE RETAINER RH	\$	167.48
1	PANEL SUB-ASSY, QUARTER, RH	\$	1,099.46
1	LINER, REAR WHEEL HOUSE, RH	\$	176.09
1	COVER, FLOOR UNDER, RH	\$	220.50
1	COVER, FLOOR UNDER, LH	\$	304.92
1	COVER, REAR FLOOR	\$	290.43
1	COVER, DECK TRIM, REAR	\$	159.39
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	824.46
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	428.19
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$	329.49
1	COVER, REAR COMBINATION LAMP, RH	\$	88.41
<b>TOTAL</b>		<b>\$</b>	<b>5,372.15</b>
25%		<b>\$</b>	<b>1,343.04</b>
		<b>\$</b>	<b>4,029.11</b>

**SPECIAL NETT**

1SET	PARKING AID	\$	700.00
1	REAR BUMPER CLIP	\$	65.00
1	END PANEL INNER TRIM CLIP	\$	60.00
1	REAR BUMPER PROTECTOR	\$	180.00
2	WINDSCREEN SEALANT	\$	150.00
1	WINDSCREEN MOULDING	\$	200.00
1	WINDSCREEN INNER SPONGE SEAL	\$	130.00
<b>TOTAL</b>		<b>\$</b>	<b>1,485.00</b>
<b>TOTAL PARTS</b>		<b>\$</b>	<b>5,514.11</b>

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**SHC5262S****AAD2407-****LABOUR**

To rust-proofing of the affected areas. \$ 600.00

Putty and **spray painting** of the affected portion. \$ 1,200.00

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same \$ 2,000.00

To transfer of **tailgate fittings and conduct water** seepage test. \$ 170.00

To Remove And Refit **Rear W/Screen Glass** To Facilitate Bodywork Repair. \$ 170.00

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ 380.00

To transfer of **tailgate fittings and conduct water** seepage test. \$ 170.00

To reinstall rear bumper **parking sensor**. \$ 170.00

To check steering geometry and computer **wheel alignment** \$ 220.00

To Transfer Of **Fender** Fittings, Attachments And Perform Water Seepage Test. \$ 170.00

**TOTAL** \$ **5,250.00**

**OVERALL TOTAL** \$ **10,764.11**