



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 2225L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TAILGATE	TO REPAIR SEE LABOUR	2,355.20	-
1	TAILGATE EMBLEM VELLFIRE	NECESSARY	90.00	90.00
1	REAR BUMPER	DEFORMED	850.00	850.00
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	62.40	-
1	REAR BUMPER TOWING COVER	DEFORMED	80.00	80.00
1	REAR BUMPER REFLECTOR	CRACKED	110.00	110.00
1	REAR BUMPER SENSOR	NOT NECESSARY	230.00	-
1	REAR CONCAVE BUMPER	DEFORMED	320.00	320.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	810.00	-
	LESS 25% DISCOUNT		-1,226.90	-362.50
			3,680.70	1,087.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
			20.00	20.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR END PANEL.		1,200.00	300.00
	TO SPRAY PAINT AFFECTED AREA.		1,200.00	600.00
	TUFF COAT.		200.00	30.00
	WIRING CHECK.		80.00	30.00
	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.	NOT NECESSARY	280.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
			3,040.00	1,010.00
	<b>GRAND TOTAL</b>		<b>6,740.70</b>	<b>2,117.50</b>

Report Ref No. CS/INC24070475/Aqh3m4(N)



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,700.00</b>
---	--	--	-----------------

Report Ref No. CS/INC24070475/Aqh3m4(N)

TOTAL FOR SPARE PARTS: \$ 3,700.70 \$ 1,107.50

TOTAL FOR LABOUR : \$ 3,040.00 \$ 1,010.00

TOTAL REPAIR COST: \$ 6,740.70 \$ 2,117.50

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.