

CS/ICS24070476/Aqp3

ASSIGNMENT

From: _____ Date: _____
 Estin: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To In Vehicle No: _____
 at Work m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SNQ2186D Yr Regn: 2016 June
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Nissan Qashqai C.D. 1997
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 124707 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: SJNFBAJ1141687298
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/45R19
 R: 225/45R19

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____
 Survey held at HD Perfect
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction	COE Expiry
	<u>TP ECICS</u>	
	<u>LS \$3750, 5 days (Red \$6873.30, 65%)</u>	Estimate given during : Yes ☒ No ☐
		1st Survey
	MV :	
	PV :	
	Nett :	
		<u>200E</u>

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: 5
 Resurvey No. of Trip: 1

Survey Fee:
 Transportation: _____
 Photos _____
 Others _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Insp (\$ _____)

Report Format: MER-TP

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 29.07.2024

TO : ECICS MOTOR CLAIMS DEPTS
VEHICLE NO : SNQ2186D
MODEL : NISSAN QASHQAI
DATE OF ACCIDENT : 28.07.2024
TIME OF ACCIDENT : 01:25 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehd</i>	1	\$ 788.70	\$ 788.70
2	REAR BUMPER REFLECTOR <i>LHA cmlhd</i>	2	\$ 59.50	\$ 119.00
3	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 28.50	\$ 28.50
4	REAR BUMPER SIDE RETAINER (FRONT) <i>new</i>	2	\$ 39.50	\$ 79.00
5	REAR BUMPER REINFORCEMENT <i>new Dehd</i>	1	\$ 691.50	\$ 691.50
6	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 285.30	\$ 570.60
7	REAR BUMPER LOWER BRACKET <i>new</i>	4	\$ 49.50	\$ 198.00
8	REAR BUMPER SPONGE <i>cmlhd</i>	1	\$ 173.80	\$ 173.80
9	REAR FENDER INNER COWLING <i>new</i>	2	\$ 207.90	\$ 415.80
10	REAR FENDER ARCED GARNISH <i>RA cmlhd</i>	2	\$ 531.30	\$ 1,062.60
11	TAIL LAMP <i>new</i>	2	\$ 528.50	\$ 1,057.00
12	TAILGATE LOGO <i>new new</i>	1	\$ 52.50	\$ 52.50
13	TAILGATE EMBLEM 'QASHQAI' <i>new</i>	1	\$ 80.90	\$ 80.90
14	TAILGATE LOCK DETECTOR <i>new</i>	1	\$ 396.40	\$ 396.40
15	TAILGATE INNER LOCK <i>new</i>	1	\$ 172.80	\$ 172.80
16	TAILGATE WEATHER STRIP <i>new</i>	1	\$ 222.40	\$ 222.40
17	REAR END PANEL <i>Dehd</i>	1	\$ 570.60	\$ 570.60
18	REAR END PANEL TOP GARNISH <i>Dehd</i>	1	\$ 119.50	\$ 119.50
19	REAR TOOLS SPONGE COMPARTMENT <i>new</i>	2	\$ 368.70	\$ 737.40

TO : ECICS MOTOR CLAIMS DEPTS
 VEHICLE NO : SNQ2186D
 MODEL : NISSAN QASHQAI
 DATE OF ACCIDENT : 28.07.2024
 TIME OF ACCIDENT : 01:25 HOURS

TOTAL PRICE \$ 7,537.00
 LESS 10% \$ 753.70
 SUB TOTAL PRICE \$ 6,783.30

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
2	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
3	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
4	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
5	REAR WHEEL ARCL CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
6	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00 <i>20</i>
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
8	REVERSE SENSOR (4PCS) <i>new</i>	1	\$ 480.00	\$ 480.00 <i>300</i>

TOTAL \$ 980.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	<i>600</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING AND BULB CHECK	\$ 80.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>

TO : ECICS MOTOR CLAIMS DEPTS
VEHICLE NO : SNQ2186D
MODEL : NISSAN QASHQAI
DATE OF ACCIDENT : 28.07.2024
TIME OF ACCIDENT : 01:25 HOURS

7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
---	--	-----------	---

TOTAL

3840

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,783.30
TOTAL LABOUR COST : \$ 3,840.00
TOTAL REPAIR COST : \$ 10,623.30

Adrian Lj
2/s 30/09/24
05 days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: