


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 29.07.2024

TO : ECICS MOTOR CLAIMS DEPTS
VEHICLE NO : SNQ2186D
MODEL : NISSAN QASHQAI
DATE OF ACCIDENT : 28.07.2024
TIME OF ACCIDENT : 01:25 HOURS

Xiao Chen.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehd</i>	1	\$ 788.70	\$ 788.70
2	REAR BUMPER REFLECTOR <i>LA cmlhd</i>	2	\$ 59.50	\$ 119.00
3	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 28.50	\$ 28.50
4	REAR BUMPER SIDE RETAINER (FRONT) <i>new</i>	2	\$ 39.50	\$ 79.00
5	REAR BUMPER REINFORCEMENT <i>new Dehd</i>	1	\$ 691.50	\$ 691.50
6	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 285.30	\$ 570.60
7	REAR BUMPER LOWER BRACKET <i>new</i>	4	\$ 49.50	\$ 198.00
8	REAR BUMPER SPONGE <i>cmlhd</i>	1	\$ 173.80	\$ 173.80
9	REAR FENDER INNER COWLING <i>new</i>	2	\$ 207.90	\$ 415.80
10	REAR FENDER ARCED GARNISH <i>RA cmlhd</i>	2	\$ 531.30	\$ 1,062.60
11	TAIL LAMP <i>new</i>	2	\$ 528.50	\$ 1,057.00
12	TAILGATE LOGO <i>new new</i>	1	\$ 52.50	\$ 52.50
13	TAILGATE EMBLEM 'QASHQAI' <i>new</i>	1	\$ 80.90	\$ 80.90
14	TAILGATE LOCK DETECTOR <i>new</i>	1	\$ 396.40	\$ 396.40
15	TAILGATE INNER LOCK <i>new</i>	1	\$ 172.80	\$ 172.80
16	TAILGATE WEATHER STRIP <i>new cut</i>	1	\$ 222.40	\$ 222.40
17	REAR END PANEL <i>Dehd</i>	1	\$ 570.60	\$ 570.60
18	REAR END PANEL TOP GARNISH <i>Dehd</i>	1	\$ 119.50	\$ 119.50
19	REAR TOOLS SPONGE COMPARTMENT <i>new</i>	2	\$ 368.70	\$ 737.40

✓
59.50
+
+
✓ 619.
+
+
✓
X
537.30
+
X
+
+
+
✓
✓
✓
+

TO : ECICS MOTOR CLAIMS DEPTS
 VEHICLE NO : SNQ2186D
 MODEL : NISSAN QASHQAI
 DATE OF ACCIDENT : 28.07.2024
 TIME OF ACCIDENT : 01:25 HOURS

TOTAL PRICE \$ 7,537.00
 LESS 10% \$ 753.70
 SUB TOTAL PRICE \$ 6,783.30

3165.70
 2849.13

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
2	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
3	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
4	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
5	REAR WHEEL ARCL CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
6	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00 <i>20</i>
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
8	REVERSE SENSOR (4PCS) <i>2nd</i>	1	\$ 480.00	\$ 480.00 <i>300</i>

430 TOTAL \$ 980.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	600
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 80.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50

TO : ECICS MOTOR CLAIMS DEPTS
VEHICLE NO : SNQ2186D
MODEL : NISSAN QASHQAI
DATE OF ACCIDENT : 28.07.2024
TIME OF ACCIDENT : 01:25 HOURS

7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
---	--	-----------	---

1400

TOTAL

3840

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,783.30
TOTAL LABOUR COST : \$ 3,840.00
TOTAL REPAIR COST : \$ 10,623.30

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lij
2/s 30/09/24

05 days

total: 4679.13

A/S: 3750 ✓