

PRECISE AUTO SERVICE

NO.1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO.REG.NO.: 35766600C

GST REG. NO.: 35766600C

Date : 20/08/2024

Accident Date : 26/07/2024

OUR REF :BNV 6018/T/24

AOU CHOY LOO

C/o : 1 Kaki Bukit Ave 6 #02-34

Singapore (417883)

ESTIMATE BILL ON VEHICLE NO. BNV 6018

MODEL : KIA SPORTAGE

CHASSIS NO : KNAPM81AMG7101071

NOTIFY ITEM

Rockel Panel Garnish - LH

Rockel Panel Garnish Clips

10pcs @ 3.00

Rear Wheel Arc Garnish

Rear Wheel Arc Garnish Clips

8pcs @ 3.00

grand 580.00 ✓

net 30.00 ✓

grand 320.00 ✓

net 24.00 X

954.00

Less Discount 10%: 95.40

858.60

SPECIAL NETT ITEM

Rear LH Sport Rim

net 650.00 X

LABOUR CHARGE

To Remove & Refix Rear LH Sport Rim & Conduct Wheel Balancing.

net 150.00 X

To Check and Adjust Computer Wheel Alignment.

120.00 60

To Respray Affected Areas.

380.00 380

To Renew Damages Parts, Straighten & Repair Rear LH Door & Aligned All Parts.

450.00 280

2,608.60

GST 9%: 234.77

TOTAL AMOUNT : 2,843.37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1

Acknowledged by BNV 6018/T/24

Signature:

Date:

1-930
100
837.00
690
1527
223
124

not Authorized
den
marcus
30/7/24
2/s \$1200/
alph. Marc
2 days.

LKK - Marcus
Date in/out: 14/08/24 @ 15/08/24