

Not With-ordered
 11 Imp 8320dp
 Resurvey After Painting
 4 days

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722
 Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SKQ8373B
 Vehicle Model : Mazda 5

Date : 21.02.2025

Estimate Repair Cost

No.	Qty	Parts List Items
1	1	Front bumper 1021
2	2	Front bumper retainers
3	1	Front bumper fog lamp cover LH
4	1	Front bumper fog lamp cover chrome LH
5	1 set	Front bumper clips
6	1	Front fender LH 780
7	1	Headlamp LH 1779
8	1	Front nozzle washer LH

Bu	\$	1,193.18	✓
	\$	31.52	✓
	\$	55.80	X
	\$	129.13	X
	\$	40.00	✓
Bu	\$	2,975.03	✓
mg	\$	2,975.03	✓
	\$	114.63	X
	\$	7,514.32	

201

Total

Parts Special Nett Items

9	1	Front wheel rim LH
10	1	Front tyre LH

\$	Net	250.00	✓
\$	in	200.00	X
\$		450.00	

Total Parts

\$ 7,964.32

Labour

- Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.
- To putty and respray painting on affected areas.
- To remove, replace front bonnet and fender fittings to facilitate repair.
- To remove, replace front wheel rim and tyre.
- To check wiring and lightings.

\$	1,200.00	400
\$	1,000.00	400
\$	300.00	X
\$	150.00	200
\$	80.00	200

Total Labour

\$ 2,730.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Parts and Labour

\$ 10,694.32