

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CS/AIG24070483/ENP3E2**Date:** 27/09/2024REFERENCE

|                   |                |                  |            |                        |
|-------------------|----------------|------------------|------------|------------------------|
| Insured/Claimant: | CHAI KHAI BOON | Policy No:       | 1800102739 |                        |
| Date of Loss:     | 29/07/2024     | Nature of Claim: | OD         | Claim No: 5942106117SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                      |             |                   |
|-----------------------------|--------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMD2748M</b>                      |             |                   |
| Make & Model:               | AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) | Engine No:  | CHZ959033         |
| Reg. Date:                  | 13/08/2018 (Man. Year: 2018)         | Chassis No: | WAUZZZGA4JA096305 |
| Colour:                     | Grey                                 | Odometer:   | 73400 km          |
| Engine Capacity:            | 999 cc                               |             |                   |
| Market Value/New Car Price: | S\$78,000.00                         |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b>    |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 215/60 R16       | Rear Tyre Size:  | 215/60 R16       |
| Front Left Side:  | Bridgestone 5 mm | Rear Left Side:  | Bridgestone 5 mm |
| Front Right Side: | Bridgestone 5 mm | Rear Right Side: | Bridgestone 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                | 11,777.00         | 1,486.48          | 10,290.52         | 87.38         |
| Miscellaneous Items                  | 0.00              | 0.00              | 0.00              |               |
| Labour                               | 6,832.00          | 2,172.00          | 4,660.00          | 68.21         |
| Paintwork Labour                     | 0.00              | 0.00              | 0.00              |               |
| Towing                               | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b> | <b>18,609.00</b>  | <b>3,658.48</b>   | <b>14,950.52</b>  | <b>80.34</b>  |
| <b>- Excess (\$\$)</b>               | 400.00            | 400.00            | 0.00              | 0.00          |
| <b>(\$\$)</b>                        | 18,209.00         | 3,258.48          | 14,950.52         | 82.11         |
| <b>+ GST 9.00/9.00% (\$\$)</b>       | 1,638.81          | 293.26            | 1,345.55          | 82.11         |
| <b>Nett Amount (\$\$)</b>            | <b>19,847.81</b>  | <b>3,551.74</b>   | <b>16,296.07</b>  | <b>82.11</b>  |

INSPECTION

|                             |            |               |                                                                        |
|-----------------------------|------------|---------------|------------------------------------------------------------------------|
| Date of Assignment:         | 30/07/2024 |               |                                                                        |
| Date Inspected:             | 01/08/2024 | Inspected At: | Premium Automobiles Pte Ltd (UBI)<br>55 Ubi Road 1<br>Singapore 408699 |
| Estimated Period of Repair: | 5.0 days   |               |                                                                        |

**Adjuster:** CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                                | Condition     | Repairer's               | Amount                         |
|-----|-----|----------|--------------------------------------------|---------------|--------------------------|--------------------------------|
| 1   | 1   |          | *FRONT FENDER - RH                         | Repair        | 1,365.00 FS              | *- FS                          |
| 2   | 1   |          | *FRONT FENDER ATTACHMENT PARTS - RH        | Not Necessary | 47.00 FS                 | *- FS                          |
| 3   | 1   |          | *FRONT FENDER BRACKET - RH REAR            | Not Necessary | 20.00 FS                 | *- FS                          |
| 4   | 1   |          | *FRONT FENDER BRACKET - RH CENTER          | Not Necessary | 62.00 FS                 | *- FS                          |
| 5   | 1   |          | *FRONT FENDER BRACKET - RH FRONT           | Not Necessary | 20.00 FS                 | *- FS                          |
| 6   | 6   |          | *FRONT FENDER RIVET - RH                   | Not Necessary | 26.00 FS                 | *- FS                          |
| 7   | 1   |          | *FRONT FENDER BRACE - RH                   | Not Necessary | 67.00 FS                 | *- FS                          |
| 8   | 1   |          | *FRONT FENDER CLOSING ELEMENT - RH         | Not Necessary | 42.00 FS                 | *- FS                          |
| 9   | 1   |          | *FRONT FENDER INSULATION - RH              | Not Necessary | 129.00 FS                | *- FS                          |
| 10  | 1   |          | *FRONT FENDER SEAL - RH UPPER              | Not Necessary | 47.00 FS                 | *- FS                          |
| 11  | 1   |          | *FRONT HEADLIGHT BRACKET - RH              | Not Necessary | 56.00 FS                 | *- FS                          |
| 12  | 1   |          | *FRONT WHEEL HOUSING LINER - RH            | Not Necessary | 236.00 FS                | *- FS                          |
| 13  | 1   |          | *FRONT WHEEL HOUSING LINER ATTACHMENT PART | Not Necessary | 67.00 FS                 | *- FS                          |
| 14  | 1   |          | *FRONT WHEEL ARCH COVER - LH / RH          | O/S Cut       | 802.00 FS                | *320.40 FS                     |
| 15  | 1   |          | *FRONT DOOR - RH                           | Repair        | 3,152.00 FS              | *- FS                          |
| 16  | 1   |          | *FRONT DOOR ATTACHMENT PARTS - RH          | Not Necessary | 3,152.00 FS              | *- FS                          |
| 17  | 1   |          | *FRONT DOOR CATCH - RH                     | Not Necessary | 300.00 FS                | *- FS                          |
| 18  | 1   |          | *FRONT DOOR HINGE UPPER PART - RH UPPER    | Not Necessary | 53.00 FS                 | *- FS                          |
| 19  | 1   |          | *FRONT DOOR HINGE LOWER PART - RH UPPER    | Not Necessary | 60.00 FS                 | *- FS                          |
| 20  | 1   |          | *FRONT DOOR HINGE UPPER PART - RH LOWER    | Not Necessary | 55.00 FS                 | *- FS                          |
| 21  | 1   |          | *FRONT DOOR HINGE LOWER PART - RH UPPER    | Not Necessary | 60.00 FS                 | *- FS                          |
| 22  | 1   |          | *FRONT DOOR LOWER COVER - RH               | Cut           | 304.00 FS                | *242.80 FS                     |
| 23  | 1   |          | *FRONT ALUMINIUM RIM - RH                  | Cut           | 1,150.00 FS              | *920.00 FS                     |
| 24  | 1   |          | *FRONT ALUMINIUM RIM RUBBER VALVE - RH     | Necessary     | 5.00 FS                  | *3.28 FS                       |
| 25  | 1   |          | *SUNDRIES                                  | Not Necessary | 500.00 FS                | *- FS                          |
|     |     |          |                                            |               | <b>Total Parts (S\$)</b> | <b>11,777.00      1,486.48</b> |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars                                                                                                                                                           | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                                                                                                       |          |                 |                 |
| 1                              | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER                                               | New      | 360.00          | 0.00            |
| 2                              | TO REMOVE AND TRANSFER RHS FRONT DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES                                                                 | New      | 400.00          | 0.00            |
| 3                              | TO REMOVE AND TRANSFER FRONT BUMPER. TO DISMANTLE AND RENEW RHS FRONT FENDER AND RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New      | 3,200.00        | 500.00          |
| 4                              | TO RESPRAY RHS FRONT FENDER AND RHS FRONT DOOR                                                                                                                        | New      | 2,300.00        | 1,100.00        |
| 5                              | TO RENEW RIM AND CARRY OUT WHEEL ALIGNMENT                                                                                                                            | New      | 280.00          | 280.00          |
| 6                              | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                                         | New      | 292.00          | 292.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                                                       |          | <b>6,832.00</b> | <b>2,172.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >