



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Prime Tambayong	Cust No/Name	/Prime Tambayong
9 Bright Hill Drive	Reg No/Reg Date	SNK5491J / 25/04/2023
Singapore 579600	Date In/Mileage	/ 0
Contact No Mobile: 91815848	Chassis No	KNARH81GMP5142821
	Engine No	G4FTNH044348
	Make/Model	KIA/SORENTO 1.6 A SR G918
	Colour/Trim	ABP / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00087	Cash	27/07/2024/ 09:54		1015/ Vikneswaran Naidu A	11148		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E WHEELALIGNMENT120LB&P To Conduct Computerize Full Wheel Alignment							120.00
E PNT88000 RENEW FRT BUMPER, FRT RH FENDER, FRT RH DOOR, REPAIR RR RHS DOOR AND RENEW DAMAGED PARTS							3840.00
E PNT98000 SPRAY FRT BUMPER, FRT RHS FENDER, FRT RHS DOOR, RR RHS DOOR							2400.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							280.00
A 10028901 CHECK WIRING AND ELECTRICAL							100.00
E PNT88000 REMOVE ADN REFIT SENSOR							100.00
E PNT88000 REMOVE AND REFIT/TRANSFER FRT RHS DOOR TRIM AND MECHANISM							160.00
M SUNDRY RENEW FRT RHS RIM							120.00
M SUNDRY ANTI RUST PROOFING							150.00
M SUNDRY SUPPLY PNL SEALANT							100.00
M SUNDRY SUNDRIES							100.00
M COVER-FR BUMPER UPR				1.00	661.00	00.00	661.00
M MOULDING-FRONT BUMPER,RH				1.00	69.00	00.00	69.00
M GARNISH ASSY-FNDR SIDE,RH				1.00	76.00	00.00	76.00
M GARNISH ASSY-FR DR SIDE RH				1.00	196.00	00.00	196.00
M GARNISH ASSY-RR DR SIDE,RH				1.00	210.00	00.00	210.00
M GRILLE-FRONT BUMPER				1.00	319.00	00.00	319.00
M PANEL ASSY-FRONT DOOR,RH				1.00	1411.00	00.00	1411.00
M PANEL ASSY-FENDER,RH				1.00	772.00	00.00	772.00
M GARNISH ASSY-DR FRAME RH				1.00	48.00	00.00	48.00
M MOULDING ASSY-FRT DR FRAME,RH				1.00	46.00	00.00	46.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Prime Tambayong 9 Bright Hill Drive Singapore 579600 Contact No Mobile: 91815848	Cust No/Name	/Prime Tambayong
	Reg No/Reg Date	SNK5491J / 25/04/2023
	Date In/Mileage	/ 0
	Chassis No	KNARH81GMP5142821
	Engine No	G4FTNH044348
	Make/Model	KIA/SORENTO 1.6 A SR G918
	Colour/Trim	ABP / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00087	Cash	27/07/2024/ 09:54		1015/ Vikneswaran Naidu A	11148		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	WHEEL ASSY-ALUMINIUM			1.00	900.00	00.00	900.00
M	VALVE-TPMS			1.00	159.00	00.00	159.00

Estimate

Confirm & accepted by

	Nett	12,337.00
9% GST on	12337.00	1110.33
Total Payable		13,447.33

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.