

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

7P111
Daphne.

SELAMAT BIN SUKIYAR
819 WOODLANDS ST 82 #03-347
SINGAPORE 730819

TAX INVOICE

Contact : 98471600

Repair Code : CLM16320

Date in : 10/06/2024

Vehicle Num. : SLV2923R

Model : RENAULT GRAND SCENIC IV 1.5 DCI AT EU6

Chassis/Eng# : VF1RFA00258596330/K9KF649D016458

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>torn</i>	1	1512.00	✓ 1,512.00
REAR BUMPER CENTER BRACKET <i>crackd</i>	1	417.00	✓ 417.00
REAR BUMPER LOWER BRACKET <i>crackd</i>	2	90.00	✓ 180.00
REAR BUMPER LOWER DIFFUSER <i>Rehd</i>	1	391.00	✓ 391.00
REAR BUMPER LOWER LID <i>Rehd</i>	1	677.00	✓ 677.00
REAR BUMPER REFLECTOR L/R <i>ren</i>	2	317.00	+ 634.00
REAR BUMPER REINFORCEMENT <i>ren</i>	1	680.00	+ 680.00
REAR BUMPER REVERSE SENSOR <i>2 pieces damaged</i>	4	266.00	532 1,064.00
REAR BUMPER REVERSE SENSOR 'O' RING <i>make 2 piece</i>	4	20.00	40 80.00
REAR BUMPER REVERSE SENSOR HOLDER <i>n</i>	4	88.00	100 352.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>ren</i>	1	450.00	+ 450.00
REAR BUMPER SIDE RETAINER L/R <i>ren</i>	2	117.00	+ 234.00
REAR END PANEL <i>ren</i>	1	1200.00	+ 1,200.00
REAR END PANEL INNER TOP GARNISH <i>ren</i>	1	300.00	+ 300.00
REAR EXHAUST GASKET <i>ren</i>	1	110.00	+ 110.00
REAR EXHAUST HEAT SHIELD COVER <i>3 improved</i>	1	306.00	306.00
REAR EXHAUST RUBBER MOUNTING <i>for x ren</i>	2	97.00	+ 194.00
REAR EXHAUST SILENCER BOX <i>ren</i>	1	1406.00	+ 1,406.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SELAMAT BIN SUKIYAR
819 WOODLANDS ST 82 #03-347
SINGAPORE 730819

Contact : 98471600

TAX INVOICE

Repair Code : CLM16320

Date in : 10/06/2024

Vehicle Num. : SLV2923R

Model : RENAULT GRAND SCENIC IV 1.5 DCI AT EU6

Chassis/Eng# : VF1RFA00258596330/K9KF649D016458

REAR LH FENDER INNER SHIELD COVER <i>new</i>	1	276.00	+	276.00
REAR TAILGATE <i>ComLd</i>	1	2327.00	✓	2,327.00
REAR TAILGATE 'LOGO' EMBLEM <i>2</i>	1	237.00	135	237.00
REAR TAILGATE 'RENAULT' EMBLEM <i>1</i>	1	216.00	120	216.00
REAR TAILGATE 'SCENIC' EMBLEM <i>1</i>	1	210.00	115	210.00
REAR TAILGATE HINGES L/R <i>new</i>	2	150.00	+	300.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	60.00	+	120.00
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	312.00	7832	312.00
REAR TAILGATE OUTER COVER <i>DelLd</i>	1	1478.00	980	1,478.00
REAR TAILGATE WEATHER STRIP <i>new</i>	1	300.00	704880	300.00
REAR TAILLAMP LOWER BRACKET L/R <i>new</i>	2	150.00	+	300.00
Subtotal before discount				16,263.00
Percentage discount 10%				1,626.30
Sub-total 1				14,636.70
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	30	80.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	40.00	+	40.00
REAR LH FENDER INNER SHIELD COVER CLIPS - SET <i>new</i>	1	30.00	+	30.00
REAR TAILGATE WINDSCREEN SEAL <i>new</i>	1	80.00	40	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SELAMAT BIN SUKIYAR
819 WOODLANDS ST 82 #03-347
SINGAPORE 730819

Contact : 98471600

TAX INVOICE

Repair Code : CLM16320
Date in : 10/06/2024
Vehicle Num. : SLV2923R
Model : RENAULT GRAND SCENIC IV 1.5 DCI AT EU6
Chassis/Eng# : VF1RFA00258596330/K9KF649D016458

REAR TAILGATE WINDSCREEN SEALANT	1	80.00	40	80.00
			110	
	Subtotal before discount			310.00
Percentage discount	0%			0.00
	Sub-total 2			310.00
	Parts-total			14,946.70

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.
To remove, reinstall tailgate windscreen
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
To apply anti-rust chemical on repaired and replaced panel.
To remove, reinstall tailgate mechanism and check for function

50 80.00
120 150.00
30 80.00
900 1,000.00
80 120.00
400 1,000.00
+ 120.00
60 80.00
1140
Labour Total 2,630.00
Parts & Labour Total 17,576.70

*** This is a computer-generated document which requires no signature.***

page 3

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adnan C
2/S 11/06/24
04 Dyr
Total: 8258.80

U/S: 6.6K ✓