

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBW2950A

Model : Tmax560

S/No	Parts Description	QTY	List Price	Nett Price	Remark
1	Front cover		\$ 365.00		cut ✓
2	Headlamp cover		\$ 480.00		cut ✓
3	Headlamp assy		\$ 1,950.00	1350	cut ✓
4	Front fender		\$ 295.00		cut ✓
5	Fender		\$ 265.00		cut ✓
6	Front fork assy	12	\$ 1,750.00	750.42	9.800.00
7	Fork under bracket		\$ 330.00	m X	X
8	Steering cone bearing		\$ 150.00	m X	X
9	Alignment repair			\$ 350.00	X m
10	Towing			\$ 80.00	✓
11	Labour			\$ 350.00	200
12					280
13			3505		
14		10%	3154.50		
15			280		
16					
17		9	3434.50		
18			02 days		
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					

Less 10%

\$ 5,585.00 \$ 780.00
\$ 558.50
\$ 5,026.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: