

MCR MOTORS PTE.LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-53 SINGAPORE 415875

Vehicle number: SNM3744H

Make & Model: Toyota Sienta Hybrid

Chassis number: MXPL101138451

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate <i>Dented</i>	1	\$ 1,817.57
2	Tailgate centre emblem <i>Nec</i>	1	\$ 86.60
3	Tailgate "Hybrid" emblem <i>new</i>	1	\$ 121.39
4	Tailgate windscreen glass rubber moulding <i>new</i>	1	\$ 93.10
5	Tailgate lock <i>new</i>	1	\$ 463.40
6	Tailgate lock catch <i>new</i>	1	\$ 45.33
7	Tailgate inner trim board <i>new</i>	1	\$ 324.80
8	Tailgate inner trim board clips <i>new</i>	1set	\$ 80.00
9	Tailgate wiper motor <i>new</i>	1	\$ 673.10
10	Tailgate RH damper stay <i>new</i>	1	\$ 233.10
11	Tailgate LH damper stay <i>new</i>	1	\$ 233.10
12	Tailgate outer garnish <i>new</i>	1	\$ 738.52
13	Tailgate outer garnish clips <i>new</i>	1set	\$ 70.00
14	Tailgate weatherstrip <i>new</i>	1	\$ 369.05
15	Tailgate reverse camera <i>new</i>	1	\$ 849.39
16	Rear bumper <i>Dented</i>	1	\$ 711.23
17	Rear bumper clips <i>new</i>	1set	\$ 80.00
18	Rear bumper towing cover <i>new</i>	1	\$ 28.94
19	Rear bumper RH side retainer <i>new</i>	1	\$ 147.20
20	Rear bumper LH side retainer <i>new</i>	1	\$ 147.20
21	Rear bumper RH side reverse sensor <i>new</i>	1	\$ 329.60
22	Rear bumper RH centre reverse sensor <i>new</i>	1	\$ 329.60
23	Rear bumper LH centre reverse sensor <i>new</i>	1	\$ 329.60
24	Rear bumper LH side reverse sensor <i>new</i>	1	\$ 329.60
25	Rear bumper RH side reflector <i>new</i>	1	\$ 168.44
26	Rear bumper LH side reflector <i>new</i>	1	\$ 168.44
27	RH taillamp	1	\$ 553.28
28	RH taillamp gasket	1	\$ 34.21
29	RH taillamp lock clips <i>Not</i>	1set	\$ 35.00
30	LH taillamp <i>Nec</i>	1	\$ 553.28
31	LH taillamp gasket	1	\$ 34.21
32	LH taillamp lock clips	1set	\$ 35.00
33	End panel <i>Dented</i>	1	\$ 402.61
34	End panel inner garnish <i>Dented</i>	1	\$ 265.36
35	End panel inner garnish clips <i>new</i>	1set	\$ 50.00
36	End panel antenna sensor <i>Dented</i>	1	\$ 109.60
37	Rear RH fender inner trim <i>new</i>	1	\$ 687.43
38	Rear RH fender inner trim clips <i>new</i>	1set	\$ 70.00

1380

210

595

30

20

39	Rear LH fender inner trim <i>Quibed</i>	1	\$ 687.43	✓
40	Rear LH fender inner trim clips <i>new</i>	1set	\$ 70.00	30
41	Rear spare tyre upper board <i>new</i>	1	\$ 342.19	+

\$ 12,897.90
 Parts less 25% \$ 3,224.48
 Total: \$ 9,673.43

No.	Special Nett Items	Qty	Amount S\$	
1	Tailgate glass sealant <i>3mm</i>	1	\$ 80.00	40
2	Tailgate glass inner seal	1	\$ 60.00	30
3	End panel joint sealant <i>new</i>	1	\$ 80.00	60
4	Rear number plate <i>new</i>	1	\$ 80.00	+

Total: \$ 300.00

No.	Labour and painting	Amount S\$	
1	Labour charges to the affected and consistent areas	\$ 1,500.00	702
2	Spray painting on affected and consistent areas and panels	\$ 1,400.00	202
3	Check wiring and lighting system on affected areas	\$ 80.00	30
4	Apply rust coating chemical on affected areas and panels	\$ 100.00	60
5	Remove and refit tailgate windscreen glass to assist repair	\$ 220.00	120
6	Remove and replace tailgate reverse camera to assist repair	\$ 100.00	50
7	Remove and replace tailgate inner mechansim to new tailgate	\$ 150.00	60
8	Remove and replace rear bumper reverse sensors to assist repairs (4 pcs)	\$ 120.00	50
9	Remove and replace rear inner trims and boards to assist repairs	\$ 350.00	60

Labour total: \$ 4,020.00

Final total: \$ 13,993.43

Admin
1/5 8/07/24.
06 Pays