

ASS. REC. BY:

REF:

CS/PCI24070490/Dnp³

ASSIGNMENT

Front:

Date:

Estimated Cost:

OB / TP / NS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

DAC Accident Report:

Consistent? : Yes or No

GA / PR Seen:

Consistent? : Yes or No

Est. Repair:

5 days

Res.: Yes or No

Lump Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBG 464LM

Yr Regn:

17 Aug 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN NV 200

c.c. 1461

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

214328

T/Radio:

Insured / Std / NI / NA

Eng/No:

K9KLC400D056655

G/No:

VSKYBAM 2070143292

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

175/70 R14

R:

11

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

26/07/2024

D.O.A.

30/07/2024

Survey held at

Ajay Auto AMC

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rst Capitel

MV 32K

LTA 12K

24/08/24

pneul 454,701- with 5 days 7m

(red, \$11082.670%)

Date/Time, File Pass to?

1

: Prel. Report

Date/Time, File Return to?

2

2

: Final Report

Report Format:

Lump Sum / LB. (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S+RS \$

Photos

Others

TOTAL




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY

Reference No.: 270724

Date: 27.07.2024

A&G Equipment Pte Ltd
20 Tech Park Crescent
Singapore 638112.

Nissan NV200

[WITHOUT PREJUDICE SAVE AS TO COSTS]

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate Repair Cost for Motorcycle Reg. No: GBG 4641 M

1 Pc. RH Side Mirror Assy. <i>HH</i>	599.80	X
1 Pc. RH Side Quarter Glass Moulding with Glass Assy. <i>Dam</i>	310.00	✓
1 Pc. RH Fender <i>Buc</i>	498.90	✓
1 Pc. RH Fender Dust Garnish <i>broken</i>	295.60	✓ 266.80
10 Pcs. RH Fender Dust Garnish Clips <i>HH</i> @ 5.00	50.00	15/- SH
1 Pc. RH Fender Corner Bracket <i>HH</i>	135.00	X
1 Pc. RH Fender Side Retainer <i>HH</i>	120.00	X
1 Pc. RH Fender Signal Lamp <i>dislodged</i>	133.00	✓
1 Pc. RH Fender Inner Housing <i>HH</i>	991.00	X
1 Pc. RH Fender Top Beam <i>Dam</i>	145.00	✓
1 Pc. RH Head Lamp Assy. <i>cut / mainly broken</i>	899.60	✓
1 Pc. RH Head Lamp Holder <i>HH</i>	149.50	X
1 Pc. Wiper Tank <i>defunct / mainly broken</i>	351.00	✓ 225.40
1 Pc. Grille <i>Dam</i>	491.00	✓ 397.00
1 Pc. Grille Logo <i>SH</i>	189.00	X
1 Pc. Grille Chrome <i>HH</i>	258.00	X
6 Pcs. Grille Clips <i>HH</i> @ 6.00	36.00	15/- SH
1 Pc. Bumper Top <i>o/s crack / defunct</i>	391.00	✓ 328.30
1 Pc. Bumper Bottom <i>Dam</i>	632.10	✓
10 Pcs. Bumper Clips <i>HH</i> @ 5.00	50.00	15/- SH
1 Pc. Bumper Beam <i>HH</i>	291.00	X
1 Pc. Bumper Reinforcement <i>HH</i>	499.00	X
1 Pc. Support Panel <i>HH</i>	1,089.00	X
1 Pc. Support Garnish <i>HH</i>	196.60	X
1 Pc. Wheel Cap <i>broken / cut</i>	128.00	✓
1 Pc. Rim <i>HH</i>	299.00	X
1 Pc. Tyre <i>HH</i>	210.00	X
1 Pc. RH Front Knuckle Arm <i>HH</i>	498.50	X
1 Pc. RH Front Wheel Bearing <i>HH</i>	210.00	X
1 Pc. RH Front Wheel Hub <i>HH</i>	315.00	X
1 Pc. RH Front Absorber <i>HH</i>	420.00	X
1 Pc. Bonnet <i>Dam</i>	991.00	✓ 858.60




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



1 Pc. Quarter Glass Sealant & Kit HCC

120.00 30/- SN

1 pc RH door sticker

50.00 25/- SN

4,822.70

Total (Panels / Parts):

11,001.60 (SGD)

1070

4,340.43

SN 100.00

LABOR CHARGES

To remove & refit wiring & repair check wiring.

150.00 30/-

To remove & refit quarter glass.

150.00 40/-

To remove & refit undercarriage affected damaged Parts.

400.00 HH

To press hup bearing & renew.

120.00 HH

To knocking, welding, straightening repair & renew All accident affected area.

1,200.00 700/-

To remove & refit radiator, air-con condenser & top-up Air-con gas.

280.00 HH

To respray painting on all accident affected damaged Area.

1,200.00 600/-

To rush proof all accident affected area.

1460.00

120.00 30/-

To check & adjust computer wheel alignment.

120.00 60/-

Total (Labor Charges):

3,740.00 (SGD)

30/07/2024 @ 1700W
NA Actual

5900.43

TOTAL COST SUMMARY

2/line 5 days

4/s 4,700/-

PANELS / PARTS

11,001.60

LABOR CHARGES

3,740.00

Grand Total:

14,741.60 (SGD)

2 Kk Auto