



BAN HOCK HIN
Co., Pte Ltd

3027

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

ECICS LIMITED
T TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
Singapore 038987

ATTN: ECICS LIMITED

VEHICLE NO. : FBD252U
MAKE/MODEL : YAM / MT-09

NO. : 47203

DATE : 29/07/2024
CLAIM NO. : 12554
POLICY NO. : MC/00948716/02

FROM : RAYMOND

*not allowed
in
normal
2/5 # 2450
4 days
31/7/24
when the item is
Art side? report never indicate*

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 51141 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$27.00	54.00
2	BAR HANDLE P/N: 79314 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$223.00	223.00
3	BEARING P/N: 52490 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$17.00	34.00
4	BRACKET FOOTREST REAR LH P/N: 57909 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$91.00	91.00
5	COOLANT (BMW) P/N: 56295 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$47.00	47.00
6	COVER ASSY P/N: 65193 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$73.00	73.00
7	COVER CRANKCASE 1 P/N: 56273 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$209.00	209.00
8	COVER SIDE RADIATOR LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$90.00	90.00
9	COVER SIDE RADIATOR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$90.00	90.00

*47203 *

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:



bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	DAMPER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00 X
11	EMBLEM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	22.00
12	EMBLEM, YAMAHA - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	11.00
13	FOOTREST REAR 1 P/N: 57540 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	30.00 X
14	FULL SYSTEM (LEOVINCE) LV ONE EVO - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5,972.00	5,972.00 X
15	GASKET P/N: 47142 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00 X
16	GASKET COVER MAGNET P/N: 56274 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	23.00
17	LABOUR P/N: 06766	Supply/Install	10.00	\$85.00	850.00
18	LAMP SIGNAL FRONT LH P/N: 61973 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
19	LAMP SIGNAL FRONT RH P/N: 61683 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00 X
20	LEVER BRAKE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,240.00	1,240.00 X
21	LEVER CLUTCH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,240.00	1,240.00
22	MID PIN COTTER P/N: 18575 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	6.00 X
23	MIRROR LH P/N: 48240 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	71.00
24	MIRROR RH P/N: 47686 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	71.00
* 25	MT09 ENGINE SLIDER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$775.00	775.00

*47203 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
26	MUDGUARD FRONT P/N: 79794 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$249.00	249.00 X
27	O-RING P/N: 58409 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00 X
28	O-RING P/N: 58203 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00 X
29	O-RING P/N: 58424 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00 X
30	O-RING (WATER PUMP) P/N: 27469 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00 X
31	O-RING WATER PIPE P/N: 72239 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00 X
32	RADIATOR COMP P/N: 51036 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$492.00	492.00
33	RIM FRONT ASSY P/N: 52492 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$889.00	889.00 X
34	Scoop, AIR 2 P/N: 61992 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$112.00	112.00 X
35	SEAL P/N: 78356 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00 X
36	SEAL OIL (25X40X5) P/N: 27548 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$13.00	26.00 X
37	SLIDER ENGINE (EVOTECH) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$287.00	287.00
38	SLIDER WHEEL FRONT (EVOTECH) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$148.00	148.00
39	VALVE TYRE 11.3MM BLACK (RACING VALVE) P/N: 43496 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$41.00	41.00 X

SUB TOTAL

\$13,601.00

GST @ 9 %

\$1,224.09

GRAND TOTAL (SGD)

\$14,825.09

*47203 *



bizSAFE



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	50% deposit required before ordering of parts.				

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*47203 *

