

TP STRIDES
80 ADV-L-1
L-2
L-3
L-4

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

Section A - Accident Details

Registration Number	SHD6499P
Case Reference Number	TAX/07/24/2096
Registration Date	3/11/2017
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	VETRIVEL S/O RAMAMOORTHY
Type of Accident	Side Swipe
Accident Date and Time	27/7/2024 2:40 PM
Accident Reported Date and Time	29/7/2024 10:42 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24121954
Special Instruction to ARC, if any	TP/ TOWED
Prepared Date and Time	29/7/2024 11:18 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00
Total Spray Cost	\$2,392.00	\$0.00
Total Spare Part Cost	\$7,264.94	\$0.00
Total Other Cost	\$1,839.76	\$0.00
TOTAL COST	\$12,510.70	\$0.00
ump Sum Total	\$12,500.00	\$0.00
Number of Repair Days	10.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date		
Signature		x
Remarks		

Steve (LKK)

30/7/24, 4:00 PM

W 12

L/S

M

AC M

5 dys

6

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



CamScanner



CamScanner

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodland
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicab
TO REPAIR LH PORTION	\$1,014.00	600 + 200 (supp)
Total Labour	\$1,014.00	= 800

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO RESPRAY FRONT DOOR LH	\$378.00	200
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	200
TO RESRAY REAR DOOR LH	\$378.00	200
TO RESPRAY CENTRE PILLAR LH	\$220.00	? -X- 200
TO RESPRAY REAR FENDER LH	\$378.00	200
TO RESPRAY RIM	\$220.00	80
TO RESPRAY FRONT HOOD	\$378.00	X
TO RESPRAY ROOF TOP PANEL	\$220.00	X
Total Spray Painting & Panel Beating	\$2,392.00	680 + 200 (supp)

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TOWING CHARGE	\$56.00	/ nnc
TO WASH AND VACUUM	\$60.00	X nn
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	30 / nnc
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	30 / nnc
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	80 / nnc
TO REMOVE AND REFIT TYRE	\$120.00	20 / nnc
TO TRANSFER DOOR MECHANISM	\$120.00	50 / nnc
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$593.76	/ nnc
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00	? X
TO REPLACE SUNDRY PARTS	\$100.00	X nn
Total Other Costs	\$1,839.76	= 859.76

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	25.00	\$1,055.85	Replace X R	
			STICKER LOGO (FRT DOOR)	1.00	\$60.00	0.00	\$60.00 /	Replace / nnc	
		6131247040	PILLAR, CENTER BODY, OUTER LH	1.00	\$349.50	25.00	\$262.13	Replace X	nn
		7586047900	MOULDING ASSY, BODY ROCKER PANEL, LH	1.00	\$649.10	25.00	\$486.83	Replace	X R
		6700447210	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,401.70	25.00	\$1,051.28 /	Replace / nn	
		6876020122	HINGE ASSY, REAR DOOR, UPPER LH	1.00	\$107.00	25.00	\$80.25	Replace ?	bt
		6878052031	HINGE ASSY, REAR DOOR, LOWER LH	1.00	\$93.90	25.00	\$70.43	Replace ?	bt
		8571047150	DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR, LH	1.00	\$996.60	25.00	\$747.45	Replace ?	nn
		6980447020	DOOR REAR WINDOW REGULATOR SUB-ASSY, LH	1.00	\$223.50	25.00	\$167.63	Replace ?	bt
		6863047050	CHECK ASSY, REAR DOOR	1.00	\$199.40	25.00	\$149.55	Replace ?	nn

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		6787247051	WEATHERSTRIP, REAR DOOR LH	1.00	\$174.40	25.00	\$130.80	Replace ?	nn
		6787247051	WEATHERSTRIP, REAR DOOR LH	1.00	\$194.60	25.00	\$145.95	Replace ?	torn
		6906052280	DOOR LOCK REAR, LH	1.00	\$607.90	25.00	\$455.92	Replace ?	jammed
		6783633030	DOOR REAR LOCK COVER	1.00	\$10.00	25.00	\$7.50	Replace X	nn
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	25.00	\$707.33 /	Replace /	nn
		6563847060	LINER, REAR FENDER, LH	1.00	\$151.10	25.00	\$113.32 /	Replace /	CRU
		4261147450	WHEEL, DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace X	R
		4245076020	HUB & BEARING ASSY WITH SPEED SENSOR, REAR AXLE, RH & LH	1.00	\$644.10	25.00	\$483.08	Replace ?	nn
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace X	nn
		4853080791	ABSORBER SET, SHOCK, REAR RH & LH	1.00	\$137.50	25.00	\$103.13	Replace ?	nn
		4879047010	ARM ASSY, UPPER CONTROL, REAR LH	1.00	\$455.00	25.00	\$341.25	Replace ?	nn
			STICKER PETROL ONLY	1.00	\$7.80	0.00	\$7.80 /	Replace -	NEK
		5330147110	HOOD SUB-ASSY	1.00	\$1,066.30	25.00	\$799.72	Replace X (increased)	nn
Total					\$12,043.34		\$9,081.17		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Ct
Total									