

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 08/08/2024

User ID : PohSuan

Section A - Accident Details

Registration Number	SHD6499P
Case Reference Number	TAX/07/24/2096
Registration Date	3/Nov/2017
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	VETRIVEL S/O RAMAMOORTHY
Type of Accident	Side Swipe
Accident Date and Time	27/Jul/2024 2:40 PM
Accident Reported Date and Time	29/Jul/2024 10:42 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24121954
Special Instruction to ARC, if any	TP/ TOWED
Prepared Date and Time	29/Jul/2024 11:18 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,264.00	\$800.00
Total Spray Cost	\$2,612.00	\$1,080.00
Total Spare Part Cost	\$9,459.21	\$2,638.99
Total Other Cost	\$1,839.76	\$859.76
TOTAL COST	\$15,174.97	\$5,378.75
Lump Sum Total	\$15,150.00	\$5,400.00 (L/S)
Number of Repair Days	12.0	6.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN (LKK) / FCI
ARC / Surveyor Sign Off Date	02/08/2024 3:21 PM	02/08/2024 3:08 PM
Signature		
Remarks	NBV INITIAL = 10 DAY WITH SUPP = 2 DAYS TOTAL = 12 DAYS	INITIAL = 5 DAYS / EXTEND = 1 DAY REQ TOWING INVOICE L/S REPAIR / AFTER PAINT PHOTO, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR STEVE CHEN (LKK) / HP: 010-9429 541 / Email : stevechen@lkkauto.com

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-2408-0061	Invoice Number	
Quotation Date	08.08.2024	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$600.00
TO REPAIR CENTER PILLAR LH	\$250.00	\$200.00
Total Labour	\$1,264.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	\$200.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY CENTRE PILLAR LH	\$220.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$220.00	\$80.00
TO RESPRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY ROOF TOP PANEL	\$220.00	\$0.00
TO RESPRAY CENTER PILLAR LH	\$220.00	\$200.00
Total Spray Painting & Panel Beating	\$2,612.00	\$1,080.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$56.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$80.00
TO REMOVE AND REFIT TYRE	\$120.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$50.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$593.76	\$593.76
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,839.76	\$859.76

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5330147110	HOOD SUB-ASSY	0.00	\$1,066.30	0.00	\$0.00	Replace	Not Given
			STICKER PETROL ONLY	1.00	\$7.80	0.00	\$7.80	Replace	Replace
		4879047010	ARM ASSY, UPPER CONTROL, REAR LH	0.00	\$455.00	0.00	\$0.00	Replace	Check
		4853080791	ABSORBER SET, SHOCK, REAR RH & LH	0.00	\$137.50	0.00	\$0.00	Replace	Check
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		4245076020	HUB & BEARING ASSY WITH SPEED SENSOR ,	0.00	\$644.10	0.00	\$0.00	Replace	Not Given
		4261147450	WHEEL, DISC	1.00	\$2,036.30	100.00	\$0.00	Replace	Repair
		6563847060	LINER, REAR FENDER , LH	1.00	\$151.10	25.00	\$113.32	Replace	Replace
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	25.00	\$707.33	Replace	Replace
		6783633030	DOOR REAR LOCK COVER	0.00	\$10.00	0.00	\$0.00	Replace	Not Given
		6906052280	DOOR LOCK REAR , LH	0.00	\$607.90	0.00	\$0.00	Replace	Check
		6787247051	WEATHERSTRIP, REAR DOOR LH	0.00	\$194.60	0.00	\$0.00	Replace	Check
		6787247051	WEATHERSTRIP, REAR DOOR LH	0.00	\$174.40	0.00	\$0.00	Replace	Check
		6863047050	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Check
		6980447020	DOOR REAR WINDOW REGULATOR SUB-ASSY, LH	0.00	\$223.50	0.00	\$0.00	Replace	Check
		8571047150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Check
		6878052031	HINGE ASSY, REAR DOOR , LOWER LH	0.00	\$93.90	0.00	\$0.00	Replace	Check
		6876020122	HINGE ASSY, REAR DOOR , UPPER LH	0.00	\$107.00	0.00	\$0.00	Replace	Check
		6700447210	PANEL SUB-ASSY, REAR DOOR , LH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	Replace
		7586047900	MOULDING ASSY, BODY ROCKER PANEL , LH	1.00	\$649.10	100.00	\$0.00	Replace	Repair
		6131247040	PILLAR, CENTER BODY, OUTER LH	0.00	\$349.50	0.00	\$0.00	Replace	Not Given
			STICKER LOGO (FRT DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	100.00	\$0.00	Replace	Repair
Total					\$12,043.34		\$1,939.73		

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		7586047900	MOULDING ASSY, BODY ROCKER PANEL , LH	1.00	\$649.10	100.00	\$0.00	Replace	Repair
		6876020122	HINGE ASSY, REAR DOOR , UPPER LH	1.00	\$107.00	25.00	\$80.25	Replace	Replace
		6878052031	HINGE ASSY, REAR DOOR , LOWER LH	1.00	\$93.90	25.00	\$70.43	Replace	Replace
		6980447020	DOOR REAR WINDOW REGULATOR SUB-ASSY, LH	1.00	\$223.50	25.00	\$167.63	Replace	Replace
		8571047150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Not Given
		6863047050	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given
		6787247051	WEATHERSTRIP, REAR DOOR LH	1.00	\$194.60	25.00	\$145.95	Replace	Replace
		6906052280	DOOR LOCK REAR , LH	1.00	\$607.90	25.00	\$455.92	Replace	Replace
		8215447250	WIRE, REAR DOOR, LH	1.00	\$268.00	25.00	\$201.00	Replace	Replace
		6233247050	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	1.00	\$317.10	25.00	\$237.83	Replace	Replace
Total					3,657.10		1,359.01		

Page 3 of 3