

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP / TP RES / OD RES / EVA / INV / MV

To In: _____ Vehicle No: _____

at W: _____

of _____

Insured: _____

Policy: _____

Claims: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remarks: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PP Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SG45986D Yr Regn: 2016, March

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Forester C.D. 1998

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 205424 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JFISJGR85GG069231

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18

R: 225/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 31/07/24

Survey held at Chih Chuan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S, Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Liberty

COE Expiry

Estimate given during: Yes (✓)

1st Survey: No ()

MV: 32K

PV: 18.5K

Nett: 13.5K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS: \$1

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve (\$

Report Format:

Report Format:

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No.: 50600700J

Name: Chia Chee Kiong (Xie ZhiQiang)

Address: c/o Blk 3006 Ubi Rd 1

#01-336 Singapore 408700

Date: 24-Jul-24

Vehicle No.: SGU 5986 D

Model: Subaru Forester

Items:

S/N	Description	Amount
1 pc	Front bumper <i>Dehd</i>	\$ 692.00 nett ✓
2 pcs	Bumper side retainer (\$39.50 x 2) <i>can't see</i>	\$ 79.00 nett <i>39.50</i>
1 pc	Front bumper grille <i>cut</i>	\$ 382.50 nett ✓
1 pc	Front bumper grille chrome <i>cut</i>	\$ 205.00 nett ✓
1 pc	Front bumper washer cover LHS <i>foreign not a can't see</i>	\$ 88.50 nett +
1 pc	Front bumper washer mount LHS	\$ 155.00 nett ✓
1 pc	Front bumper <i>Top</i> garnish <i>new</i>	\$ 165.00 nett +
1 pc	Front bumper side garnish upper LHS <i>missing</i>	\$ 56.50 nett ✓
1 pc	Front bumper side garnish lower LHS <i>new</i>	\$ 36.50 nett +
1 pc	Front bumper fog lamp LHS <i>can't see</i>	\$ 335.60 nett ✓
1 pc	Front bumper fog lamp cover LHS <i>cut</i>	\$ 98.00 nett ✓
1 pc	Front bumper inner garnish LHS <i>new</i>	\$ 195.00 nett +
1 pc	Front reinforcement <i>Dehd</i>	\$ 361.20 nett ✓
2 pcs	Front bumper inner sponge <i>new</i>	\$ 186.20 nett +
1 pc	Front headlamp LHS <i>cut</i>	\$ 2,550.00 nett ✓
1 pc	Front headlamp lower bracket LHS <i>can't see</i>	\$ 89.50 nett ✓
1 pc	Front number plate housing <i>new</i>	\$ 68.50 nett +
1 pc	Front bonnet centre grille <i>new</i>	\$ 245.20 nett +
1 pc	Front bonnet centre grille chrome <i>new</i>	\$ 223.00 nett +
1 pc	Front fender inner garnish LHS <i>new torn</i>	\$ 195.50 nett ✓
1 pc	Front fender LHS <i>Repair</i>	repair +
		\$ 6,047.70
	Less 10%	\$ 604.77
	Total	\$ 5,442.93

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No.: 50600700J

Special Nett Items:

- | | | |
|-------|----------------------------------|------------|
| 1 set | Front Bumper clips | <i>xxu</i> |
| 1 set | Front bumper garnish clips | <i>xxu</i> |
| 1 set | Front fender inner garnish clips | <i>xxu</i> |
| 1 set | Front number plate with housing | <i>But</i> |

\$	50.00	<i>30</i>
\$	50.00	<i>+</i>
\$	50.00	<i>+</i>
\$	45.00	<i>✓</i>
<u>\$</u>	<u>195.00</u>	

Labour

- | | | | | |
|----|---|----|--------|------------|
| 1) | To check wiring, lighting and resetting head lamps focusing | \$ | 50.00 | <i>30</i> |
| | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damage consistent to the accident. (including all repair parts) | | | |
| 3) | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident. | \$ | 700.00 | <i>400</i> |
| 4) | | \$ | 800.00 | <i>400</i> |

<u>\$</u>	<u>1,550.00</u>	
-----------	-----------------	--

Adrian Lj
2/3. 31/07/28
042p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: