

CS/LIP24070495/Aqh3

ASSIGNMENT

From: _____ Date: _____
 Estin: ~~Estin~~ _____
 OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MV
 To In: _____ Vehicle No: _____
 at W: _____
 of _____
 Insured: _____
 Policy: _____
 Claims: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____
 (Policy Condition)

N/S	O/S

Remark: Vehicle had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PP Seen: _____ Consistent?: Yes or No
 Est. Repair: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SG45986D Yr Regn: 2016, March
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Subaru Forester C.D. 1998
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 205424 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JFISJGR85GG069231
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/55R18
 R: 225/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO YOKO or
 Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 31/07/24
 Survey held at Chih Chuan
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front N/S, Front
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Liberty</u>
	<u>LS \$4000, 4 days (Red \$3529.93, 47%)</u>
	<u>MV: 32K</u>
	<u>PV: 18.5K</u>
	<u>Nett: 13.5K</u>
	<u>COE Expiry:</u>
	<u>Estimate given during: Yes (✓)</u>
	<u>1st Survey: No (✓)</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) 17/01 Typist ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

Report Form: TP

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No.: 50600700J

Name: Chia Chee Kiong (Xie ZhiQiang)

Address: c/o Blk 3006 Ubi Rd 1

#01-336 Singapore 408700

Date: 24-Jul-24

Vehicle No.: SGU 5986 D

Model: Subaru Forester

Items:

S/N	Description	Amount
1 pc	Front bumper <i>Rehnd</i>	\$ 692.00 nett ✓
2 pcs	Bumper side retainer (\$39.50 x 2) <i>can't find</i>	\$ 79.00 nett <i>39.50</i>
1 pc	Front bumper grille <i>cut</i>	\$ 382.50 nett ✓
1 pc	Front bumper grille chrome <i>cut</i>	\$ 205.00 nett ✓
1 pc	Front bumper washer cover LHS <i>foreign not a can't find</i>	\$ 88.50 nett +
1 pc	Front bumper washer mount LHS	\$ 155.00 nett ✓
1 pc	Front bumper <i>Top</i> garnish <i>new</i>	\$ 165.00 nett +
1 pc	Front bumper side garnish upper LHS <i>missing</i>	\$ 56.50 nett ✓
1 pc	Front bumper side garnish lower LHS <i>new</i>	\$ 36.50 nett +
1 pc	Front bumper fog lamp LHS <i>can't find</i>	\$ 335.60 nett ✓
1 pc	Front bumper fog lamp cover LHS <i>cut</i>	\$ 98.00 nett ✓
1 pc	Front bumper inner garnish LHS <i>new</i>	\$ 195.00 nett +
1 pc	Front reinforcement <i>Dehnd</i>	\$ 361.20 nett ✓
2 pcs	Front bumper inner sponge <i>new</i>	\$ 186.20 nett +
1 pc	Front headlamp LHS <i>cut</i>	\$ 2,550.00 nett ✓
1 pc	Front headlamp lower bracket LHS <i>can't find</i>	\$ 89.50 nett ✓
1 pc	Front number plate housing <i>new</i>	\$ 68.50 nett +
1 pc	Front bonnet centre grille <i>new</i>	\$ 245.20 nett +
1 pc	Front bonnet centre grille chrome <i>new</i>	\$ 223.00 nett +
1 pc	Front fender inner garnish LHS <i>new torn</i>	\$ 195.50 nett ✓
1 pc	Front fender LHS <i>Repair</i>	repair +
		\$ 6,047.70
	Less 10%	\$ 604.77
	Total	\$ 5,442.93

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No.: 50600700J

Special Nett Items:

- | | | |
|-------|----------------------------------|------------|
| 1 set | Front Bumper clips | <i>xxu</i> |
| 1 set | Front bumper garnish clips | <i>xxu</i> |
| 1 set | Front fender inner garnish clips | <i>xxu</i> |
| 1 set | Front number plate with housing | <i>But</i> |

\$	50.00	<i>30</i>
\$	50.00	<i>+</i>
\$	50.00	<i>+</i>
\$	45.00	<i>✓</i>
<u>\$ 195.00</u>		

Labour

- | | | |
|----|---|----------------------|
| 1) | To check wiring, lighting and resetting head lamps focusing | \$ 50.00 <i>30</i> |
| | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damage consistent to the accident. (including all repair parts) | \$ 700.00 <i>400</i> |
| 3) | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident. | \$ 800.00 <i>400</i> |
| 4) | | <u>\$ 1,550.00</u> |

Adrian Lj
2/3. 31/07/28
042p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: