

Not Authored
Penny B4 paint
81284.88

AAD2407-013

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5868U

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

30 JUL 2024

SHC5868U

JTDKB3FU103096704

200303878K

TOYOTA

PRIUS GEN 4

2/7/2024

SNC9024R/CHINA

31/3/2023

PART

- 1 UNIT ASSY, HEADLAMP, LH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 LINER, FRONT FENDER, LH
- 1 EMBLEM, SIDE PANEL
- 1 COVER, FRONT BUMPER
- 1 SUPPORT SUB-ASSY, RADIATOR, LH
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 COVER, FRONT BUMPER HOLE, LH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 MOULDING, FRONT BUMPER SIDE, LH

LIST

\$	3,325.56	X
\$	1,236.69	X
\$	265.55	X
\$	68.88	✓
\$	659.40	✓
\$	308.91	X
\$	100.91	X
\$	902.16	✓
\$	38.22	✓
\$	532.88	X
\$	224.70	X
\$	100.49	X
\$	59.85	X
\$	74.97	X
\$	120.86	X
TOTAL	\$ 8,020.03	
25%	\$ 2,005.01	
	\$ 6,015.02	

Special Nett

- 1SET BUMPER CLIP FRT
- 1SET FRNT BUMPER RETAINER CLIP
- 1SET FENDER CLIP
- 1 FENDER LINER CLIP

\$	65.00	6050
\$	85.00	X
\$	130.00	X
\$	65.00	X

Trans-cab Auto Services Pte Ltd**AAD2407-013**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5868U**TOTAL \$ 345.00****TOTAL PARTS \$ 2,300.00****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i>	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	<i>200</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i>	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	<i>440</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i>	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>100</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X

TOTAL \$ 5,100.00**Over All Total \$ 13,415.02***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: