

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		Ms Tong Sui Min Frances 1 Mount Echo Park Singapore 248765 Mobile: 96869032		
			Document No. 0				
			Document Date 29/07/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AGH30R	NFXLK S4	21/03/2019	SGJ8212S	0	31883	79/DS/SGJ8212S
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
AGH300214474		2ARJ211514	60	Ong Wen Hong	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY TP INS:MS FIRST CAPITAL TP VEH:SHD7258L DATE OF ACC:27/07/2024 NUMBER OF REPAIR DAYS: SURVEY BY:				50	100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				300	400.00
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS				7920 7128	8712.00
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS				4592 3936	5248.00
5	B	BP-LAB2 TO CHECK WIRING SYSTEM					134.64
6	B	BP-LAB2 TO DRILL HOLE AND INSTALL FRONT & REVERS E SENSOR					396.00
7	B	BP-LAB2 TO REMOVE INTERIOR UPHOLSTERY TO FAC REP AIR					396.00
8	B	BP-LAB2 TO REMOVE AND TRANSFER DOOR COMPONENT TO NEW DOOR					792.00
9	B	BP-LAB2 TO REMOVE AND RE-INSTALL REAR SEAT & SID E TRIMS					396.00
10	B	BP-MECH2 TO REMOVE AND REPLACE FRONT SUSPENSION					792.00
11	B	BP-MECH2 TO REMOVE AND INSTALL FUEL TANK					792.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Borneo Motors**TOYOTA**

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details					
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept		S1000005 / ICFIC1	Ms Tong Sui Min Frances					
		Document No. 0	1 Mount Echo Park					
		Document Date 29/07/2024	Singapore 248765 Mobile: 96869032					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	AGH30R	NFXLK S4	21/03/2019	SGJ8212S	0	31883	79/DS/SGJ8212S	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
AGH300214474		2ARJ211514	60	Ong Wen Hong	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
12	B	BP-MECH2	TO REPLACE RIM AND WHEEL BALANCING					158.40
13	B	BP-MECH2	TO CONDUCT WHEEL ALIGNMENT					198.00
14	B	BP-MECH2	TO CONDUCT ADJUSTMENT ON BLIND SPOT SENS OR					198.00
15	B	BP-ECU2	TO RESET ECU AND REPROGRAMME					198.00
16	B	BP-WS2	TO REMOVE AND INSTALL REAR QUARTER GLASS LH					396.00
17	S	BP-SUBLET	TO SUPPLY SOLAR FILM FOR REAR QUARTER GL ASS					230.00
18	1	T42611-58330	WHEEL, DISC <i>scr</i>			2.00	3456.30	6912.60
19	2	T42603-48140	ORNAMENT SUB-ASSY <i>an xan</i>			2.00	56.10	112.20
20	3	L43212-78010	KNUCKLE, STEERING <i>7.5</i>			1.00	1032.00	1032.00
21	4	T43550-28030	HUB & BEARING ASSY <i>7.5</i>			1.00	928.20	928.20
22	5	T45510-58060	GEAR ASSY, STEERING <i>7.5</i>			1.00	2732.00	2732.00
23	6	T45047-29195	END SUB-ASSY, TIE <i>7.5</i>			1.00	285.80	285.80
24	7	T47782-28210	COVER, DISC BRAKE <i>7.5</i>			1.00	139.90	139.90
25	8	T48069-28140	ARM SUB-ASSY <i>7.5</i>			1.00	1246.40	1246.40
26	9	T48820-42030	LINK ASSY, FR <i>7.5</i>			1.00	228.10	228.10
27	0	T51201-28281	CROSSMEMBER <i>7.5</i>			1.00	3750.90	3750.90
28	1	T52119-58650 C0	COVER, FR BUMPER <i>scr</i>			1.00	3365.30	3365.30
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total		
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

Customer Copy



Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	Ms Tong Sui Min Frances 1 Mount Echo Park Singapore 248765 Mobile: 96869032
	Document No. 0	
	Document Date 29/07/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AGH30R	NFXLK S4	21/03/2019	SGJ8212S	0	31883	79/DS/SGJ8212S
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
AGH300214474	2ARJ211514	60	Ong Wen Hong	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
29	2	T52421-58020 PAD, FR BUMPER	2.00	95.60		191.20
30	3	S52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00
31	4	T52116-58090 SUPPORT, FR BUMPER	1.00	105.20		105.20
32	5	T52040-58210 COVER ASSY, FR	1.00	1696.00		1696.00
33	6	T89348-33400 RETAINER, ULTRASONIC	1.00	21.40		21.40
34	7	T89348-58290 CO RETAINER, ULTRASONIC	2.00	28.30		56.60
35	8	S52161-0K040 PIECE, RR BUMPER	6.00	5.80		34.80
36	9	T52156-58030 SUPPORT, RR BUMPER	1.00	149.80		149.80
37	0	T52156-58040 SUPPORT, RR BUMPER	1.00	157.10		157.10
38	1	T53802-58160 FENDER SUB-ASSY, FR	1.00	1998.70		1998.70
39	2	T53883-58010 SEAL, FR FENDER, LH	1.00	136.80		136.80
40	3	T53836-58050 BRACE, FR FENDER TO	1.00	64.20		64.20
41	4	T53806-58110 SHIELD SUB-ASSY,	1.00	361.40		361.40
42	5	T61602-58110 PANEL SUB-ASSY,	1.00	2339.00		2339.00
43	6	T65638-58041 LINER, RR WHEEL	1.00	359.90		359.90
44	7	T62720-58250 WINDOW ASSY,	1.00	973.30		973.30
45	8	T67002-58080 PANEL SUB-ASSY, FR	1.00	3204.30		3204.30
46	9	T75924-58010 TAPE, BLACK OUT,	1.00	54.40		54.40
47	0	T75922-58010 TAPE, BLACK OUT,	1.00	30.40		30.40
48	1	T68720-12151 HINGE ASSY, FR DOOR,	1.00	135.40		135.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

incheap

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1 Document No. 0 Document Date 29/07/2024	Ms Tong Sui Min Frances 1 Mount Echo Park Singapore 248765 Mobile: 96869032

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AGH30R	NFXLK S4	21/03/2019	SGJ8212S	0	31883	79/DS/SGJ8212S
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
AGH300214474	2ARJ211514	60	Ong Wen Hong	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
49	2	T68740-12120 HINGE ASSY, FR DOOR, <i>7xsc</i>	1.00	153.00		153.00
50	3	T67004-58080 PANEL SUB-ASSY, <i>7xsc</i>	1.00	3256.70		3256.70
51	4	T67865-58071 WEATHERSTRIP, CTR <i>7xsc</i>	1.00	203.80		203.80
52	5	T84260-58041 SENSOR ASSY, POWER <i>7xsc</i>	1.00	1211.10		1211.10
53	6	T75752-58011 MOULDING, FR DOOR <i>7xsc</i>	1.00	60.00		60.00
54	7	T75756-58030 MOULDING, FR DOOR <i>7xsc</i>	1.00	142.90		142.90
55	8	T75762-58011 MOULDING, RR DOOR <i>7xsc</i>	1.00	128.40		128.40
56	9	T75742-58030 MOULDING, RR DOOR <i>7xsc</i>	1.00	191.10		191.10
57	0	T75764-58010 MOULDING, RR DOOR <i>7xsc</i>	1.00	108.50		108.50
58	1	T75766-58030 MOULDING, RR DOOR <i>7xsc</i>	1.00	174.20		174.20
59	2	T65632-58020 PLATE, RR WHEEL <i>7xsc</i>	1.00	75.50		75.50
60	3	T76904-58060 C0 MUDGUARD SUB-ASSY, <i>7xsc</i>	1.00	1191.80		1191.80
61	4	T76906-58060 C0 MUDGUARD SUB-ASSY, <i>7xsc</i>	1.00	1123.00		1123.00
62	5	T76902-58050 C0 MUDGUARD SUB-ASSY, <i>7xsc</i>	1.00	281.20		281.20
63	6	T76908-58090 C0 MUDGUARD SUB-ASSY, <i>7xsc</i>	1.00	414.10		414.10
64	7	T81185-58650 UNIT, HEADLAMP <i>7xsc</i>	1.00	9008.90		9008.90
65	8	T48520-80426 ABSORBER SET, SHOCK, <i>7xsc</i>	1.00	660.00		660.00

Case
Hp 90010068
14 days
31/07/24
Reby by
paint

For & on behalf of Borneo Motors	Customer's Signature	Charge Summary	Total	70,782.54
LKK Auto Consultants hence notify the Repairer of the following: - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	Please acknowledge receipt of vehicle	Parts	51,245.50	GST 9.00% 6,370.43 Less 0.00 Amount Due 77,152.97
		Labour	19,307.04	
		Sublet	230.00	
		Lubrication/Fluid	0.00	
		Others	0.00	



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		Ms Tong Sui Min Frances 1 Mount Echo Park Singapore 248765 Mobile: 96869032		
			Document No.				
			0				
			Document Date				
			11/09/2024				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AGH30R	NFXLK S4	21/03/2019	SGJ8212S	0	31883	79/DS/SGJ8212S

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
AGH300214474	2ARJ211514	60	Ong Wen Hong	26/08/2024 8.00	10/09/2024 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
49	2	U76908-58090 A0 MUDGUARD SUB-ASSY,	1.00	414.10		414.10
50	3	T48520-80426 ABSORBER SET, SHOCK,	1.00	660.00		660.00
51	4	T90177-22001 NUT, LOCK <i>new</i>	1.00	10.20		10.20
52	5	T43330-59155 JOINT ASSY, LWR BALL <i>bf</i>	1.00	366.90		366.90
53	6	T48609-58020 SUPPORT SUB-ASSY, FR <i>H</i>	1.00	327.10		327.10
54	7	T48619-28010 BEARING, STRUT <i>bf</i>	1.00	57.50		57.50
55	8	T51444-58030 COVER, ENGINE UNDER, <i>new</i>	1.00	66.90		66.90
56	9	T42603-48140 ORNAMENT SUB-ASSY, <i>new</i>	1.00	56.10		56.10
57	0	U52159-58946 COVER, RR BUMPER <i>scr</i>	1.00	961.50		961.50
58	1	T68720-12151 HINGE ASSY, FR DOOR, <i>bf</i>	1.00	135.40		135.40
59	2	T68740-12120 HINGE ASSY, FR DOOR, <i>bf</i>	1.00	153.00		153.00
60	3	T89348-33400 RETAINER, ULTRASONIC <i>new</i>	2.00	21.40		42.80
61	4	T89348-58290 A0 RETAINER, ULTRASONIC <i>new</i>	2.00	28.30		56.60
62	5	T42603-48140 ORNAMENT SUB-ASSY, <i>new</i>	1.00	56.10		56.10
63	6	T53836-58050 BRACE, FR FENDER TO <i>bf</i>	1.00	64.20		64.20
64	7	U90269-06017 RIVET <i>new</i>	2.00	5.40		10.80
65	8	T81185-58600 UNIT, HEADLAMP <i>new/scr</i>	1.00	14199.40		14199.40

For & on behalf of	Customer's Signature	Charge Summary	Total	67,078.14
Borneo Motors (Singapore) Pte Ltd			GST 9.00%	6,037.03
	Please acknowledge receipt of vehicle	Parts 49,139.10		
		Labour 17,709.04		
		Sublet 230.00		
		Lubrication/Fluid 0.00	Less	0.00
		Others 0.00	Amount Due	73,115.17

Customer Copy