

GENUS PERFORMANCE

39 WOODLANDS CLOSE #03-03 MEGA @ WOODLANDS SINGAPORE 737856

POK XUE TING
39 WOODLANDS CLOSE
03-03 MEGA @ WOODLANDS
Singapore 737856
Singapore 627607

22ND March 2024

MRH + CS6502000157
Dapine

Accident date: 25th July 2024
Estimated repair cost for vehicle no: SMV3613S HONDA CIVIC

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$1,150.00 655
2	1	Rear boot lid emble logo <i>New</i>		\$120.00 55
3	1	Rear boot lid emble logo clips-SET <i>New</i>		\$80.00 x
4	1	Rear Boot Lid Civic logo <i>New</i>		\$80.00 45
5	1	Rear boot lid RH logo <i>New</i>		\$85.00 x
6	1	Rear boot lid vtec logo <i>New</i>		\$40.00 ✓
7	2	Rear Boot Lid side reflector <i>cut</i>	\$355.00	\$710.00 ✓ 558.
8	1	Rear boot lid inner rubber <i>cut</i>		\$285.00 ✓
9	1	Rear Boot Lid Number Plate <i>Dented</i>		\$100.00 50
10	1	Rear Boot Lid Inner Trim board clips-SET <i>New</i>		\$80.00 30.
11	2	Rear tail lamp <i>cracked.</i>	\$521.00	\$1,042.00 661
12	2	Rear tail lamp panel <i>Bye</i>	\$211.00	\$422.00 x
13	4	Rear tail lamp clips <i>New</i>	\$6.50	\$13.00 x
14	2	rear fender inner trim <i>new</i>	\$525.00	\$1,050.00 x
15	1	Rear fender inner trim board clips-SET <i>New</i>		\$80.00 x
16	1	Rear Bumper <i>Distorted</i>		\$950.00 667
17	2	Rear Bumper Side Bracket <i>New</i>	\$185.00	\$370.00 x
18	1	Rear Bumper reverse sensor <i>Damaged</i>		\$350.00 200.
19	1	Rear bumper clips-set <i>New</i>		\$60.00 30
20	1	Rear Bumper center lower cover <i>New</i>		\$385.00 x
21	1	Rear bumper reinforcement <i>Dented.</i>		\$688.00 361
22	1	rear bumper lower garnish <i>Behind</i>		\$285.00 ✓
23	1	rear bumper inner garnish <i>New</i>		\$415.00 x
24	2	Rear Bumper mud shield <i>New</i>	\$115.00	\$230.00 x
25	2	Rear Bumper side reflector	\$105.00	\$210.00 x
26	2	rear bumper side reflector chrome <i>New</i>	\$185.00	\$370.00 x
27	1	Rear Exhaust chome pipe <i>New</i>		\$220.00 x
28	1	end panel <i>Distorted</i>		\$825.00 548.
29	1	end panel top garnish <i>Behind</i>		\$288.00 ✓
30	1	rear spare tyre top cover <i>New</i>		\$688.00 x
31	1	rear floor panel top board		\$788.00 x
32	1	rear floor panel <i>Repair</i>		\$1,850.00 x

Rear Boot Lid Outer Garnish. *cut* 265 ✓

Rear Bumper Lower Chrome Garnish. *cut* 110
Subtotal :- \$9,052.00

Rear Bootlid Inner Trim Board *Behind* 232 ✓

Rear Bootlid Lock *Damaged* 185 ✓

5450
4440

Labour charges

To Remove & refix rear windscreen

\$150.00 X

gum

\$50.00 X

To remove & refix rear cushion

\$120.00 60

To remove & refix reverse sensor

\$100.00 50

To check wiring

\$80.00 30

Tuff kote

\$120.00 60

Panel beating

\$1,600.00 800

Spray painting

\$1,600.00 800

Subtotal :- \$3,820.00

Total:- \$12,872.00

Total: 6240

h/s: SK

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: