

# 李 汽 车 贸 易

GST REG NO. 201918537M

## ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

### ESTIMATE COST OF REPAIR

Date: 30-Jul-24

Estimate no.

1427

Plate No. FBJ6092T

Model. T-MAX500

\*Surveyor's columns\*

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	REAR RIM	\$ 850.00	q	
2	REAR RIM BEARING X2	\$ 280.00	X	
3	REAR SWING ARM	\$ 900.00	X	
4	EXHAUST PIPE	\$ 1,850.00	✓	
5	EXHAUST BRACKET	\$ 380.00	✓	
6	EXHAUST COVER	\$ 350.00	X	
7	RAER FAIRING COVER R	\$ 380.00	✓	
8	REAR FAIRING COVER L	\$ 380.00	X	
9	MAINSTAND	\$ 280.00	X	
10	REAR FOOTREST L	\$ 180.00	X	
11	FRONT FOOTREST BOARD L	\$ 350.00	✓	
12	FRONT FOOTREST UNDER COVER L	\$ 300.00	✓	
13	FRONT FAIRING PANEL COVER L	\$ 320.00	✓	
14	FRONT FORK SET	\$ 800.00	X	
15	HANDLE BAR	\$ 350.00	X	
16	MIRROR SET	\$ 280.00	X	
17	SPRAY COVERSET	\$ 480.00	280	
18	LABOUR	\$ 600.00	300	

Not Authorized  
 62563561  
 31/7/24  
 L/S #2800  
 3 days  
 20/7/24 AM 11:17

9-3265  
 102  
 2928.50  
 580  
 3518.50  
 202  
 2814

Sub Total : \$ 9,310.00  
 GST 9% \$ 8,379.00  
 Total: \$ 754.11  
 \$ 9,133.11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

\*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle\*

\*This is computer generated no signature is required.\*

Acknowledged by Repairer  
 Signature:  
 Date: