

李 汽车 贸易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatileemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 30-Jul-24

Estimate no. 1427

Plate No. FBJ6092T

Model. T-MAX500

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	REAR RIM	\$ 850.00	X	
2	REAR RIM BEARING X2	\$ 280.00	X	
3	REAR SWING ARM	\$ 900.00	X	
4	EXHAUST PIPE	\$ 1,850.00	X	
5	EXHAUST BRACKET	\$ 380.00	X	
6	EXHAUST COVER	\$ 350.00	X	
7	RAER FAIRING COVER R	\$ 380.00	X	
8	REAR FAIRING COVER L	\$ 380.00	X	
9	MAINSTAND	\$ 280.00	X	
10	REAR FOOTREST L	\$ 180.00	X	
11	FRONT FOOTREST BOARD L	\$ 350.00	X	
12	FRONT FOOTREST UNDER COVER L	\$ 300.00	X	
13	FRONT FAIRING PANEL COVER L	\$ 320.00	X	
14	FRONT FORK SET	\$ 800.00	X	
15	HANDLE BAR	\$ 350.00	X	
16	MIRROR SET	\$ 280.00	X	
17	SPRAY COVERSET	\$ 480.00	X	
18	LABOUR	\$ 600.00	X	

not Audited
31/7/24
2/5 #2800
3 days
Zhu phi. AM 11:17

9-3265
102
2938.50
580
3418.50
202
214

Sub Total : \$ 8,379.00
GST 9% \$ 754.11
Total: \$ 9,133.11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

Acknowledged by Repairer
Signature:
Date: