

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24070503/EQP3M4**Date:** 30/10/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002881240
Claimant Vehicle No :	SNF5236G	Insured Vehicle No :	FBT2116H
Date of Loss:	30/07/2024	Nature of Claim:	TP
		Claim No:	368848

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF5236G	Engine No:	HIDDEN
Make & Model:	TESLA MODEL 3 RWD, (A)	Chassis No:	LRW3F7FS8NC571820
Reg. Date:	31/05/2022 (Man. Year: 2022)	Odometer:	30036 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 ZR18	Rear Tyre Size:	235/45 ZR18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,604.59	4,313.63	1,290.96	23.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,090.00	1,410.00	680.00	32.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,694.59	5,723.63	1,970.96	25.61
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	7,694.59	4,600.00	3,094.59	40.22
+ GST 9.00/9.00% (S\$)	692.51	414.00	278.51	40.22
Nett Amount (S\$)	8,387.10	5,014.00	3,373.10	40.22

INSPECTION

Date of Assignment:	02/08/2024	
Date Inspected:	31/07/2024	Inspected At: OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2024)
Parts:	143	TESLA MODEL 3 RWD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF5236G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Broken	658.88 FL	*658.88 FL
2	1		*FRONT BUMPER	Broken	766.00 FL	*766.00 FL
3	1		*FRONT BUMPER SIDE BRACKET RH	Broken	9.34 FL	*9.34 FL
4	1		*FRONT BUMPER FOG LAMP COVER RH	Cut	6.54 FL	*6.54 FL
5	1		*FRONT BUMPER PARKING SENSOR	Malfunction	163.55 FL	*163.55 FL
6	1		*FRONT BUMPER PARKING SENSOR BRACKET	Necessary	4.67 FL	*4.67 FL
7	1		*FRONT HEADLAMP RH	Broken	1,741.00 FL	*1,741.00 FL
8	1		*FRONT FENDER RH	Dented	448.59 FL	*448.59 FL
9	1		*FRONT FENDER INNER SHIELD RH	Torn	116.82 FL	*116.82 FL
10	1		*FRONT RIM RH	Chipped	505.00 FL	*505.00 FL
11	1		*FRONT ABSORBER RH	Not Necessary	429.90 FL	*- FL
12	1		*FRONT LOWER ARM RH	Not Necessary	242.99 FL	*- FL
13	1		*FRONT LOWER LATERAL ARM RH	Not Necessary	224.29 FL	*- FL
14	1		*FRONT KNUCKLE ARM RH	Not Necessary	420.56 FL	*- FL
15	1		*FRONT WHEEL BEARING RH	Humming/Jammed	233.64 FL	*233.64 FL
16	1		*FRONT WINDSCREEN SEALANT	Necessary	100.00 FS	*50.00 FS
17	1		*FRONT IU STICKER	Necessary	40.00 FS	*25.00 FS
18	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
19	1		*FRONT FENDER INNER SHIELD CLIPS RH	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,201.77	4,779.03
- List Item Discount on L Items 10.00/10.00% (S\$)	597.18	465.40
Total Parts (S\$)	5,604.59	4,313.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST FRONT ACCIDENT AREAS & ETC	New	500.00	450.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH & ETC	New	500.00	450.00
3	LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS, FRONT WINDSCREEN SEALANT & ETC	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REPLACE FRONT RIM RH, FRONT ABSORBER RH, FRONT LOWER ARM RH, FRONT KNUCKLE ARM, FRONT WHEEL BEARING RH & ETC	New	400.00	100.00
5	LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC	New	120.00	30.00
6	TO WHEEL ALIGNMENT & BALANCING	New	100.00	80.00
7	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	200.00	150.00
8	TO CHECK WIRING & ELECTRICAL SYSTEM	New	120.00	30.00
Gross Labour Cost (\$\$)			2,090.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >