

Date: 30/07/2024
Vehicle No: SNF5236G
Model: TESLA MODEL 3 RWD
Chassis: LRW3F7FS8NC571820-2022
Reg.Year: 2022

Third Party Insurer: MSIG
Third Party Veh No: FBT2116H
Date of Accident: 30/07/2024
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT WINDSCREEN GLASS / BR	1		\$658.88
2	FRONT BUMPER / BR	1		\$766.00
3	FRONT BUMPER SIDE BRACKET RH ? BR	1		\$9.34
4	FRONT BUMPER FOG LAMP COVER RH ? CUT	1		\$6.54
5	FRONT BUMPER PARKING SENSOR ? Malfunction	1		\$163.55
6	FRONT BUMPER PARKING SENSOR BRACKET / MC	1		\$4.67
7	FRONT HEADLAMP RH ? BR	1		\$1,741.00
8	FRONT FENDER RH / DD	1		\$448.59
9	FRONT FENDER INNER SHIELD RH ✓ TH	1		\$116.82
10	FRONT RIM RH / Chipped	1		\$505.00
11	FRONT ABSORBER RH ? x nn	1		\$429.90
12	FRONT LOWER ARM RH ? x nn	1		\$242.99
13	FRONT LOWER LATERAL ARM RH ? x nn	1		\$224.29
14	FRONT KNUCKLE ARM RH ? x nn	1		\$420.56
15	FRONT WHEEL BEARING RH ? Humming/jammed	1		\$233.64
SUB TOTAL				\$5,971.77
LESS 10%				-\$597.18
PARTS TOTAL				\$5,374.59

4654.03
-10%
4188.62

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT WINDSCREEN SEALANT / MC	1		50 \$100.00
2	FRONT IU STICKER / MC	1		25 \$40.00
3	FRONT BUMPER CLIPS / MC	1		30 \$50.00
4	FRONT FENDER INNER SHIELD CLIPS RH / MC	1		20 \$40.00
S/N TOTAL				\$230.00

125

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 30/07/2024
Vehicle No: SNF5236G
Model: TESLA MODEL 3 RWD
Chassis: LRW3F7FS8NC571820-2022
Reg.Year: 2022

Third Party Insurer: MSIG
Third Party Veh No: FBT2116H
Date of Accident: 30/07/2024
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.	450 440	\$500.00	
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH & ETC.	450 440	\$500.00	
LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS, FRONT WINDSCREEN SEALANT & ETC.	120	\$150.00	
LABOUR CHARGES TO REMOVE & REPLACE FRONT RIM RH, FRONT ABSORBER RH, FRONT LOWER ARM RH, FRONT KNUCKLE ARM, FRONT WHEEL BEARING RH & ETC.	?	\$400.00	100
LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC.	30	\$120.00	
TO WHEEL ALIGNMENT & BALANCING.	80	\$100.00	
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	150 140	\$200.00	
TO CHECK WIRING & ELECTRICAL SYSTEM.	30	\$120.00	
LABOUR TOTAL		\$2,090.00	1410

TING AN

TOTAL

\$7,694.59

Stew (LKK)

31/7/24, 11.40 AM

WL R

L/S

L AL R
4 djs

5723.62

L/S - 4578.89
= 4600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Branch
9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)
Bik 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

