


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE 29.07.2024

TO : **MS FIRST CAPITAL** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNK9688H**
MODEL : **TOYOTA ALPHARD**
DATE OF ACCIDENT : 29.07.2024
TIME OF ACCIDENT : 01:25 HOURS

Vern

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>new</i>	1	\$ 683.70	\$ 683.70
2	FRONT BUMPER FOG LAMP RH <i>2nd</i>	1	\$ 516.10	\$ 516.10
3	FRONT BUMPER FOG LAMP COVER CHROME RH <i>1st</i>	1	\$ 78.90	\$ 78.90
4	FRONT BUMPER SENSOR HOLDER <i>new</i>	2	\$ 32.20	\$ 64.40
5	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 89.60	\$ 179.20
6	FRONT FENDER RH <i>Dented</i>	1	\$ 1,312.50	\$ 1,312.50
7	FENDER LOWER GUARD RH <i>Dented</i>	1	\$ 285.00	\$ 285.00
8	FRONT FENDER COWLING <i>Dented RH</i>	2	\$ 259.30	\$ 518.60
9	FRONT FENDER INNER GARNISH RH <i>new</i>	1	\$ 123.20	\$ 123.20
10	FRONT FENDER SUPPORT BRACKET RH <i>new</i>	1	\$ 85.20	\$ 85.20
11	HEADLAMP RH <i>RH cracked</i>	2	\$ 9,912.35	\$ 19,824.70
12	BONNET <i>new</i>	1	\$ 855.60	\$ 855.60
13	BONNET HINGE <i>new</i>	2	\$ 64.60	\$ 129.20
14	BONNET LOCK <i>new</i>	1	\$ 135.80	\$ 135.80
15	FRONT WHEEL SPORT RIM <i>1st</i>	1	\$ 1,808.40	\$ 1,808.40
16	FRONT ABS SENSOR RH <i>new</i>	1	\$ 543.90	\$ 543.90
17	FRONT CROSSMEMBER <i>new</i>	1	\$ 2,704.80	\$ 2,704.80
18	FRONT DRIVESHAFT RH <i>2nd</i>	1	\$ 1,534.80	\$ 1,534.80
19	FRONT STEERING RACK & PINION <i>1st</i>	1	\$ 1,955.30	\$ 1,955.30
20	FRONT KNUCKLE ARM RH <i>Dented</i>	1	\$ 734.80	\$ 734.80
21	FRONT LOWER ARM RH <i>Dented</i>	1	\$ 815.30	\$ 815.30

+
+
+
+
+
1110
259.30
9912.35
1050.50
685

TO : **MS FIRST CAPITAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNK9688H**
 MODEL : **TOYOTA ALPHARD**
 DATE OF ACCIDENT : 29.07.2024
 TIME OF ACCIDENT : 01:25 HOURS

22	FRONT STABILIZER BAR LINKAGE RH <i>new</i>	1	\$ 165.20	\$ 165.20	+
23	FRONT SHOCK ABSORBER RH <i>new</i>	1	\$ 519.10	\$ 519.10	+
24	FRONT WHEEL HUP C/W BEARING RH <i>new</i>	1	\$ 670.30	\$ 670.30	+
25	FRONT DOOR RH <i>Repair</i>	1	\$ 1,867.40	\$ 1,867.40	+
26	FRONT DOOR LOWER GUARD RH <i>Repair</i>	1	\$ 1,098.70	\$ 1,098.70	+
27	FRONT DOOR LOWER WEATHER STRIP RH <i>new</i>	1	\$ 107.60	\$ 107.60	+
28	FRONT DOOR OUTER STRIP RH <i>new</i>	1	\$ 177.60	\$ 177.60	+
29	FRONT DOOR HINGE RH <i>new</i>	1	\$ 85.10	\$ 85.10	+
30	FRONT DOOR WEATHER STRIP RH <i>new</i>	1	\$ 279.30	\$ 279.30	+

1341645 S.N. 1050
1006233
 TOTAL PRICE \$ 39,859.70
 LESS 25% \$ 9,964.93
 SUB TOTAL PRICE \$ 29,894.78

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
2	FRONT FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
3	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
4	FRONT BONNET INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	FRONT BONNET MOULDING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
6	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
7	FRONT SUPPORT PANEL BOTTOM COVER GARNISH <i>new</i>	1	\$ 60.00	\$ 60.00	+
8	FRONT FENDER INNER GARNISH CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
9	FRONT FENDER LOWER GUARD CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
10	FRONT FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
11	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 680.00	\$ 680.00	+
12	FRONT DOOR SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00	+
13	FRONT DOOR LOWER GUARD CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
14	FRONT DOOR INNER TRIM BOARD CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
15	FRONT DOOR BOTTOM GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
16	BRAKE OIL <i>new</i>	1	\$ 40.00	\$ 40.00	+

TOTAL \$ 1,750.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

TO : **MS FIRST CAPITAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNK9688H**
 MODEL : **TOYOTA ALPHARD**
 DATE OF ACCIDENT : 29.07.2024
 TIME OF ACCIDENT : 01:25 HOURS

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	500
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	500
3	TURFF COAT	\$ 250.00	30
4	WIRING CHECK	\$ 250.00	30
5	REFOCUS HEADLAMP BEAM	\$ 80.00	X
6	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	X
7	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	X
8	TRANSFER FRONT DOOR MECHANISM RH	\$ 80.00	X
9	REMOVE AND REFIX FRONT WINDOW GLASS RH	\$ 60.00	X
10	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 850.00	? 200
11	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 380.00	X
12	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
13	FOUR WHEEL ALIGNMNET	\$ 120.00	80
14	RESET ABS LIGHT	\$ 180.00	X

TO : **MS FIRST CAPITAL** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNK9688H**
MODEL : **TOYOTA ALPHARD**
DATE OF ACCIDENT : 29.07.2024
TIME OF ACCIDENT : 01:25 HOURS

15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 450.00	X
----	--	-----------	---

1340

TOTAL \$ **6,290.00**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 31,644.78
TOTAL LABOUR COST : \$ 6,290.00
TOTAL REPAIR COST : \$ 37,934.78

Adrian L
2/5 31/07/24.
05 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 12522.33

2/5: 1012

1012

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: