



Your Ref : 23/24/24/VC05/029613

Date: 22nd August 2024

Our Ref : CS/LPC24070505/Nqp3m4

M/s Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBE 4567E
ACCIDENT ON 24/07/2024**

Instruction was received to inspect the vehicle Reg. No. GBE 4567E. The inspection was conducted on 31/07/2024 at the premises of M/s Mova Automotive Pte Ltd, 15 Fan Yoong Road, Singapore 629792.

The following vehicle information was recorded:

Registration Number	: GBE 4567E
Make/Model	: Nissan Cabstar 3.0 5M/T Abs 2dr 2wd Euro 5
Year of Registration	: 2015
Body Colour	: Silver
Chassis Number	: JN1SC2F24Z0857916
Engine Capacity	: 2953 cc
Speedometer Reading	: Not Available

The vehicle caught fire. The cause of fire probably due to electrical short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	15,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	5,207.00)
Nett Liability	S\$	9,793.00
	=====	

Vehicle Inspected By:



MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.