

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|-------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-----------------|-----------------------|--|
| MS | INCOME INSURANCE LTD 75 BRAS BASAH ROAD | | Ref: | CS/INC24060082/Eqh3e2 | |
| | | | Date: | 16/07/2024 | |
| | INCOME CENTRE S | SINGAPORE 189557 | Code: | INC | |
| 1. | | | | | |
| | Insured Veh. | YR 362P | Veh. Inspected | YM 8025L | |
| | Policy No. | - | Coverage | 0 | |
| | Claim No. | MT/1274817-005 | Excess | \$0.00 | |
| | Assign From | SHAFAWATI BINTE MD RABU | Assign Date | 13/06/2024 | |
| 2. Vehicle Details | | | | | |
| | Make & Model | ISUZU NPR85LU4Y | c.c | 2999 | |
| | Engine No. | 4JJ1580407 | Year of Reg. | 14/02/2008 | |
| | Chassis No. | JAANPR85L87100066 | Colour | WHITE | |
| | Odometer | 614563 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | General | GOOD | |
| | Modification(s) | RIMS: STANDARD ALLOY RIM | | | |
| 3. | Conditions of Tyres | | | | |
| | | Size | Make | Balance (mm) | |
| | R/H Front Tyre | 7.00 R16 | GT RADIAL | 5 | |
| | L/H Front Tyre | 7.00 R16 | GT RADIAL | 5 | |
| | R/H Rear Tyre | 7.00 R16 | GT RADIAL | 5 | |
| | L/H Rear Tyre | 7.00 R16 | GT RADIAL | 5 | |
| 4. | Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. | | | | | |
| DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | |
| | Accident Date | 25/04/2024 | Inspection Date | 13/06/2024 (02:23PM) | |
| | Survey held at | RYDER AUTO PTE LTD | • | | |
| | | 2 KAKI BUKIT AVE 2 | | | |
| | #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921 | | | | |
| 5a. Remarks | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | | | |
| | | | | | |