

ESTIMATE OF REPAIR

Veh# : YM8025L

Model: ISUZU

Accident Date : 25/4/2024

14/2/2008

Location : ADMIRALTY ROAD

3P: YR362P (NTUC)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front door LH / <i>DD</i>	1,911.60	1265 /	
2	1 pc	Front door hinge LH / <i>BT</i>	121.00	/	
3	1 pc	Front door hinge (Lower) / <i>BT</i>	114.70	/	
4	1 pc	Front door LH window frame moulding <i>X</i>	90.00		
5	1 pc	Front door weatherstrip LH / <i>tn</i>	363.10	138 /	
6	1 pc	Front door weatherstrip LH lower / <i>tn</i>	140.30	/	
7	1 pc	Front door glass regulator LH <i>?</i> <i>295</i>	442.30		
8	1 pc	Front door glass regulator motor LH <i>X</i>	269.70		
9	1 pc	Front door glass channel seal LH <i>X</i>	146.90		
10	1 pc	Front door glass channel bracket LH (Front) <i>X</i>	120.20		
11	1 pc	Front door glass channel bracket LH (Rear) <i>V</i>	99.50		
12	1 pc	Front door LH door lamp <i>X</i>	245.00		
13	1 pc	Front door checker LH <i>X</i>	165.80		
14	1 pc	Front door trim board LH <i>?</i> <i>415</i>	810.40		
15	1 set	Front door trim board clip LH <i>?</i>		50.00	
16	1 pc	Front door trim plastic seal cover <i>X</i>	43.00		
17	1 pc	Front door Arch garnish LH <i>X</i>	304.60		
18	1 pc	Front door LH middle black garnish <i>W</i> / <i>CUT</i>	145.00	/	
19	1 pc	Front door lock LH <i>X</i>	155.00		
20	1 pc	Front door lock motor LH <i>X</i>	210.00		
21	1 pc	Front step garnish LH <i>X</i>	543.90		
22	1 pc	Front LH head lamp / <i>BR</i>	810.00	447 /	
23	1 pc	Front LH signal lamp / <i>BR</i>	560.00	221 /	
24	1 pc	side mirror / <i>BT</i>	80.00	/	
25	1 pc	side mirror bracket / <i>BT</i>	130.00	/	

26	1 pc	Front bumper / BR	640.00	425	
27	1 pc	Front bumper Rh & Lh Y	360.00		
28	1 pc	Front LH corner panel / BR	235.00	/	
29	1 pc	Front LH corner panel sticker / APC	235.00	60	
30	1 pc	Front LH corner panel clips / APC		60.00	15
31	1 pc	Front LH corner panel garnish X TR	45.00		
Sub-Total:			9,537.00	110.00	0.00
			15%	0%	0%
After Less %:			8,106.45	110.00	0.00
Labour					
1		To remove & refix accident damaged parts & realign affected area.	1,200.00	500	
2		To spray paint on affected area.	800.00	600	
3		To remove & refix door mechanism & check for function.	80.00	50	
4		To check wiring, layout & check for function.	100.00	30	
5		To rust proof affected area.	80.00	30	
Sub-Total:			2,260.00		
Total:			10,476.45		
Total -20%:			8,381.16		

Chan

Chan San Choon
Director
DipEng, AAE MIM,MSAE (Aust)



AL 8778 1999
24 hr accident call



Sten (LKK)

13/6/24, 2.30pm

W L

L/S

by AL Sp

5 d/s

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

L ESTIMATEPg2