

E M Solution Pte Ltd

160 Sin Ming Drive #03-19, Sin Ming Autocity

Singapore 575722

Tel: 64560226

GST/Reg. No: 201016308K

*Not Nochain
1/1 by 22800p
Pulover After Rain
4 days*

ESTIMATE

Date : 20th August 2024

Mr **Goh Shon Hai**
47 Burgundy Drive
Singapore 658841

Veh No : **SLX 8830A**
Make/Model : **Toyota Vios**
Chassis No : **MR2B23F3301118861**
Date of Acc : **29.07.24**
TP Veh No : **SJU 4961X**

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Rear Boot Lid		\$ <i>Rs</i> 947.10 ✓
2	1 pc	Rear Boot Lid Vios Emblem		\$ <i>Rs</i> 68.60 —
3	1 pc	Rear Boot Lid E Emblem		\$ <i>Rs</i> 41.55 —
4	1 pc	Rear Boot Lid Toyota Logo		\$ <i>Rs</i> 68.60 —
5	1 pc	Rear Boot Lid Mechanism Lock		\$ <i>R</i> 231.60 X
6	1 pc	Rear Bumper		\$ <i>Bu</i> 631.50 ✓
7	2 pcs	Rear Bumper Reflector L/R	\$ 121.60	\$ <i>Sn</i> 243.20 X
8	2 pcs	Rear Bumper Side Retainer L/R	\$ 89.95	\$ <i>1500</i> 179.90 ✓
9	2 pcs	Rear Bumper Bracket L/R	\$ 86.55	\$ <i>R</i> 173.10 ✓
10	1 pc	Rear End Panel		\$ <i>R</i> 780.10 ✓
11	1 pc	Rear End Panel Top Garnish		\$ <i>my nd</i> 161.90 ✓
12	1 pc	Rear Boot Weatherstrip		\$ <i>80.715n</i> 161.42 ✓
13	1 pc	Rear Spare Tire Tray		\$ <i>sn</i> 391.20 X
				\$ 4,079.77
			Less 25%	\$ 1,019.94
			Parts Total :	\$ 3,059.83
Special Nett				
1	1 set	Reverse Sensor		\$ <i>nd</i> 250.00 ✓
2	1 set	Rear Bumper Clips		\$ <i>Rs</i> 45.00 ✓
3	1 set	End Panel Top Garnish Clips		\$ <i>Rs</i> 40.00 ✓
			Special Nett :	\$ 335.00
Labour				
1	To remove & rearrange electrical wirings, check lightings		\$ 80.00	150
2	To remove & replace upholstery, trim garnishes to facilitate repairs.		\$ 100.00	300
3	To remove, transfer boot lid components		\$ 100.00	500
4	To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.		\$ 1,000.00	5000
5	Putty and respray painting on affected portions.		\$ 1,000.00	6000
6	To remove & renew reverse sensor		\$ 100.00	300
7	Rust proofing on affected portions.		\$ 100.00	300
			Labour Total :	\$ 2,480.00
			Total Parts & Labour :	\$ 5,874.83

LKK Auto Consultants hence notify the Repairer of the following:

To remove & replace boot lid components


for E M Solution Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.