

BETHLEHEM AUTO

5035 Ang Mo Kio Industrial Park 2 #01-371

H/P: 8299 6103 | TEL: 6483 0189

E-Mail: bethauto6757@gmail.com

UEN: 53347232J

To: MS FIRST CAPITAL INSURANCE LTD

Vehicle Number : SMC3179D

Vehicle Model : TOYOTA CHR

ESTIMATED REPAIR COSTS FOR ABOVE STATED VEHICLE

PARTS

QTY		AMOUNT
1	TAILGATE	\$ 1,105.20
1	TAILGATE OUTER MOULDING	\$ 698.10
1	TAILGATE CHR EMBLEM	\$ 57.60
1	TAILGATE HYBRID EMBLEM	\$ 57.60
1	TAILGATE LAMP LH	\$ 498.90
1	TAILGATE LOGO	\$ 68.60
1	TAILGATE LOCK	\$ 374.10
1	TAILGATE SWITCH	\$ 247.90
1	TAILGATE WEATHER STRIP	\$ 275.10
1	TAILGATE INNER TRIM LOWER	\$ 495.70
1	TAILGATE WINDSCREEN MOULDING	\$ 186.40
1	TAIL LAMP LH	\$ 577.40
1	REAR BUMPER	\$ 530.30
1	REAR BUMPER LOWER	\$ 400.20
2	REAR BUMPER SIDE RETAINER @ \$110.50 EACH	\$ 221.00
2	REAR BUMPER REFLECTOR GARNISH LH / RH @ \$359.10 EACH	\$ 718.20
2	REAR BUMPER REFLECTOR LH / RH @ \$109.50 EACH	\$ 219.00
1	REAR BUMPER CENTER LAMP	\$ 469.80
1	REAR BUMPER TOW HOOK COVER	\$ 75.90
1	REAR KEYLESS SENSOR	\$ 298.60
1	REAR REINFORCEMENT BAR	\$ 360.10
1	REAR END PANEL	\$ 775.70
1	REAR END PANEL TOP GARNISH	\$ 192.50

PARTS SUM: \$ 8,903.90

PARTS LESS 25%: \$ 2,225.98

PARTS TOTAL: \$ 6,677.93

SPECIAL NETT ITEMS

QTY		AMOUNT
1SET	NO. PLATE & GARNISH	\$ 80.00

1SET	REVERSE SENSOR <i>Pan</i>	\$ 250.00	220/-
1	TAILGATE WINDSCREEN SEALANT <i>HT</i>	\$ 60.00	X
1	TAILGATE WINDSCREEN DAMPING SEAL <i>HT</i>	\$ 30.00	X
1SET	TAILGATE INNER TRIM CLIPS <i>HT</i>	\$ 50.00	X
1SET	TAILGATE CENTER MOULDING CLIPS <i>HT</i>	\$ 40.00	X
1SET	REAR BUMPER CLIPS <i>HT</i>	\$ 40.00	20/-
1	REAR END PANEL SEALANT <i>HT</i>	\$ 60.00	X
1SET	REAR END PANEL TOP GARNISH CLIPS <i>HT</i>	\$ 30.00	X

LABOUR

S/N		AMOUNT	
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 900.00	500/-
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 900.00	400/-
3	TO APPLY TUFF COAT ON ALL AFFECTED AREAS	\$ 80.00	20/-
4	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	\$ 300.00	HT
5	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$ 150.00	HT
6	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	\$ 120.00	HT
7	TO RNR ALL INTERIOR UPHOLSTERY TO FACILITATE REPAIRS	\$ 200.00	HT
8	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 100.00	HT

LABOUR & S/N TOTAL: \$ 2,750.00

GRAND TOTAL ESTIMATED REPAIR COSTS: \$ 9,427.93

2801.17

L/S 2200/-

01/08/2024 @ 1200w

Net Amount

2/5m

4 days.

LKK And

Check part plus.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: