



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBR 6522C

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BALANCER	CUT	\$75.00	\$60.00
1	BAR HANDLE	SERVICEABLE	\$185.00	\$0.00
1	LH BRAKE PUMP	NOT NECESSARY	\$260.00	\$0.00
1	MIRROR	CUT	\$88.00	\$88.00
1	LH FRONT SIGNAL	CRACKED	\$78.00	\$78.00
1	LH FAIRING	CUT	\$255.00	\$255.00
1	HEAD LAMP GUARD	TO REPAIR SEE LABOUR	\$165.00	\$0.00
1	FORK UNDER BRACKET	NOT NECESSARY	\$280.00	\$0.00
1	SET FORK	SERVICEABLE	\$490.00	\$0.00
1	STEERING CONE	NOT NECESSARY	\$150.00	\$0.00
1	FRONT WHEEL SLIDE	CUT	\$120.00	\$120.00
1	LH LOWER FAIRING	CUT	\$165.00	\$165.00
1	FOOTREST PLATE	CUT	\$130.00	\$130.00
1	AT BOX COVER	CUT	\$85.00	\$85.00
1	BELTING COVER	CUT	\$175.00	\$175.00
1	MAIN STAND	TO REPAIR SEE LABOUR	\$155.00	\$0.00
1	SET EXHAUST PIPE COVER	TO REPAIR SEE LABOUR	\$285.00	\$0.00
1	BOX 55L	CUT	\$320.00	\$300.00
1	REAR FOOTREST	CUT	\$88.00	\$88.00
1	RH FOOTREST PANEL COVER	CUT	\$75.00	\$75.00
1	RH FAIRING	TO REPAIR SEE LABOUR	\$255.00	\$0.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$161.90)
			\$3,879.00	\$1,457.10

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TOWING		\$50.00	\$30.00
	ALIGNMENT		\$220.00	\$50.00
	LABOUR.INCLUSIVE OF THE REPAIR OF HEAD LAMP GUARD,MAIN STAND, SET EXHAUST PIPE COVER AND RH FAIRING		\$480.00	\$300.00
			\$750.00	\$380.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

GRAND TOTAL		\$4,629.00	\$1,837.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,450.00
Report Ref No: CS/FCI24070511/Unp3			

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.