

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKS2686C
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

ATTN: Motor Claim Department

FAX: 64153727

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 29/07/2024
TP Veh Reg No: GBD5288J

Estimate No: ES2400649/YISHUN
Date: 05 Aug 2024
Policy No: 5098461865-06
Veh Reg No: SKS2686C
Make/Model: TOYOTA COROLLA
ALTIS 1.6L CVT
Chassis No: MR053REH104527325
Engine No: 1ZR492055
Reg. Date: 02/04/2015

Not Notified
L1 Pay @ 1750/-
Running After Paint
3 days

Estimate Repair Cost to Vehicle No :SKS2686C

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT GRILLE	870.30	1 PC	CM 870.30	✓
2 FRONT GRILLE LOGO	68.40	1 PC	Ne 68.40	✓
3 FRONT GRILLE CLIPS	5.00	4 PCS	Ne 20.00	✓
4 FRONT BUMPER	878.30	1 PC	Av/BA 878.30	✓
5 FRONT BUMPER CLIPS	4.00	6 PCS	Ne 24.00	✓
			1,861.00	
		Less 25%	465.25	1,395.75
Labour				
6 REMOVE & REFIX FRT BUMPER,GRILLE,KNOCK & REPAIR FRT BUMPER REINFORCEMENT,FRT SUPPORT PANEL AND REALIGN THE SAME	400.00	1 LA	400.00	300
7 PUTTY & RESPRAY ON FRT BUMPER,FRT BONNET,SUPPORT PANEL	600.00	1 LA	600.00	540
			1,000.00	
		Less 25%	250.00	750.00
		Total		S\$ 2,145.75
		Add GST @ 9%		193.12
		Total Amount Payable		S\$ 2,338.87

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE