

Not Authorized
 L1 Surp @ 3200h
 Resurvey After Paint
 5 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : ~~SLX 7934R~~ *SLU 7636S*

Date: 29.07.2024

S/N	Parts Description	Unit Price	Amt
1	Rear fender LH	<i>Pr</i>	\$1,410.10 ✓
2	Rear fender innershield LH	<i>Pr</i>	\$291.60 X
3	Rear fender inner board LH	<i>Pr</i>	\$608.90 X
4	Rear fender protector LH	<i>Pr</i>	\$65.30 ✓
5	Sliding door roller real LH	<i>Pr</i>	\$229.40 X
6	Rear bumper assy	<i>Ad/mg cm</i>	\$695.00 ✓
7	Rear bumper side LH	<i>Ad/br</i>	\$397.00 ✓
8	Rear bumper retainer X 2	<i>N/S dit</i>	\$192.20 X
9	Rear taillamp assy LH	<i>cm</i>	\$439.80 ✓
10	Rear fuel cover	<i>Pr</i>	\$68.20 ✓
	Special Nett		
1	Rear door board clips	<i>nn</i>	\$80.00 X
2	Rear bumper clips	<i>nn</i>	\$80.00 <i>40ln</i>
3	Rear wheel rim LH <i>conv</i>	<i>Ad</i>	\$600.00 <i>100ln</i>
4	Rear tyre LH	<i>Pr</i>	\$300.00 X
5	Rear fender glass sealant LH	<i>Pr</i>	\$80.00 <i>40ln</i>

258

Labour

1	To remove and refit damaged parts, cut/weld damaged areas.	\$900.00	<i>600l</i>
2	To spray paint on affected areas.	\$1,000.00	<i>600l</i>
3	Check wiring	\$60.00	<i>20l</i>
4	Tuff coating	\$80.00	<i>30l</i>
5	To remove and refit rear garnishes and etc	\$180.00	<i>100l</i>
6	To remove and refit rear fender glass	\$120.00	<i>60l</i>
7	To conduct wheel alignment	\$120.00	<i>60l</i>

\$2,460.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: