

ASS. REC. BY:

REF:

ICS/ CS/ICS24060083/Kvp3e2

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. MPC24P00082100

Claims No. DMPC2400726H/AF

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: MIC

R: PIR

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 No Modification Panel, workshop said owner insist to see all new parts.

25/7/11 Rep @ 65501 Cuhw (red 21,767.70, 76%)

Data/Time, File Pass to?

☐

: Prel. Report

1)

Data/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

: Fines

: Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 089D

Vehicle Details

Vehicle No.: SNJ1278R
Vehicle to be Exported: No
Intended Deregistration Date: 11 Jun 2024
Vehicle Make: B.M.W.
Vehicle Model: 528i 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour: Black
Manufacturing Year: 2013
Engine No.: A0120424N20B20A
Chassis No.: WBAXG32050D121833
Maximum Power Output: 180.0 kW (241 bhp)
Open Market Value: \$47,857.00
Original Registration Date: 25 Mar 2013
First Registration Date: 25 Mar 2013
Transfer Count: 4
Actual ARF Paid: \$42,857.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 24 Mar 2033
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$106,916.00
COE Rebate Amount: \$93,925.00
Total Rebate Amount: \$93,925.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.
The information contained herein is correct as at 11 Jun 2024

OK

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM			
Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC24P00082100	Date of Loss:	11/06/2024
Vehicle Reg. No.:	SNJ1278R	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ZHU QIURONG		
Make/Model:	BMW 528i, 2.0 D/AB 2WD 4DR GAS/D NAV (A)	Vehicle Reg. Date:	25/03/2013
Vehicle Colour:	White		
Engine No:	A0120424N20B20A	Chassis No:	WBAXG32050D12183
Odometer:	252151 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5 days		
Present Location:	CONVERGENCE AUTOMOTIVE PTE LTD (HQ)		

NOT WORKING
Repair B4 paint
Est \$350k
11/06/2024 \$6550k

COST OF CLAIMS	Amount
Parts	23,547.70
Miscellaneous Items	0.00
Labour	3,890.00
Paintwork Labour	880.00
Towing	0.00
Calculated Gross Total (S\$)	28,317.70
- Excess (S\$)	600.00
(S\$)	27,717.70
+ GST 9.00% (S\$)	2,494.59
Nett Amount (S\$)	30,212.29

This claim is handled by: WONG SIANG YEE

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jun 2024)

Parts: 143 BMW 528I 2.0 D/AB 2WD 4DR GAS/D NAV (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Convergence Automotive Pte Ltd/SNJ1278R/12/06/2024 17:25

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts


No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BONNET 1500	0.00	0.00	*2,500.00 F	✓
2	1		*BONNET HINGE LH	0.00	0.00	*175.00 F	X
3	1		*BONNET HINGE RH	0.00	0.00	*175.00 F	X
4	2		*BONNET GAS ABSORBER	0.00	0.00	*270.00 F	X
5	1		*BONNET SEAL FRT	0.00	0.00	*65.00 F	X
6	1		*BONNET SEAL REAR	0.00	0.00	*85.00 F	X
7	1		*ENGINE UPPER SEAL COVER LH	0.00	0.00	*235.00 F	X
8	3		*BONNET STOP BUFFER	0.00	0.00	*30.00 F	X
9	2		*BONNET ADJUSTER	0.00	0.00	*36.00 F	X
10	1		*BONNET BONNET LOWER LOCK LH (W/ELEC) 120	0.00	0.00	*280.00 F	✓
11	1		*BONNET LOWER LOCK RH	0.00	0.00	*255.00 F	X
12	1		*BONNET UPPER LOCK LH	0.00	0.00	*115.00 F	X
13	1		*BONNET UPPER LOCK RH	0.00	0.00	*115.00 F	X
14	1		*BONNET LOCK CABLE (4)	0.00	0.00	*65.00 F	X
15	1		*FRT FENDER LH	0.00	0.00	*780.00 F	X
16	1		*FRT FENDER BRACKET (2)	0.00	0.00	*40.00 F	X
17	1		*FRT FENDER SPACER LH	0.00	0.00	*42.00 F	X
18	1		*FRT FENDER INNER SHIELD LH	0.00	0.00	*195.00 F	X
19	1		*HEADLAMP LH	0.00	0.00	*2,350.00 F	✓
20	1		*HEADLAMP LED MODULE LH (2)	0.00	0.00	*580.00 F	X
21	1		*HEADLAMP INDICATOR INSERT LH (6)	0.00	0.00	*425.00 F	X
22	1		*HEADLAMP CONTROL UNIT LH	0.00	0.00	*1,050.00 F	X
23	1		*HEADLAMP DRIVE AHL MODULE LH	0.00	0.00	*990.00 F	X
24	1		*SUPPORT HEADLAMP LWR BRACKET LH	0.00	0.00	*290.00 F	X
25	1		*SUPPORT V-STRUT BAR LH	0.00	0.00	*55.00 F	X
26	1		*SUPPORT V-STRUT BAR RH	0.00	0.00	*55.00 F	X
27	1		*SUPPORT PANEL CONNECTION FRT 420	0.00	0.00	*550.00 F	✓
28	1		*SUPPORT PANEL CONNECTION REAR	0.00	0.00	*420.00 F	X
29	1		*SUPPORT AIR DUCT	0.00	0.00	*790.00 F	X
30	1		*FRT BUMPER ORIGINAL	0.00	0.00	*1,350.00 F	✓
31	1		*FRT BUMPER HOLDER LH	0.00	0.00	*14.00 F	✓
32	1		*FRT BUMPER WASHER CAP LH	0.00	0.00	*48.00 F	✓
33	1		*FRT BUMPER WASHER CAP LEVER LH	0.00	0.00	*22.00 F	X
34	1		*FRT BUMPER WASHER CAP SPRING LH	0.00	0.00	*9.00 F	X
35	1		*FRT BUMPER WASHER CAP PLUG LH	0.00	0.00	*16.00 F	X
36	1		*FRT BUMPER LWR CTR GRILLE	0.00	0.00	*125.00 F	X
37	1		*FRT BUMPER LWR SIDE GRILLE LH	0.00	0.00	*110.00 F	X
38	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*790.00 F	X
39	1		*FRT BUMPER IMPACT ABSORBER	0.00	0.00	*150.00 F	X
40	1		*FRT BUMPER LOWER BEAM	0.00	0.00	*180.00 F	X
41	1		*FRT BUMPER LOWER BEAM BRACKET LH	0.00	0.00	*130.00 F	X
42	1		*FRT GRILLE LH	0.00	0.00	*220.00 F	X
43	1		*FRT GRILLE RH	0.00	0.00	*220.00 F	X
44	1		*FRT LOGO	0.00	0.00	*95.00 F	✓
45	1		*FRT BUMPER UNDERCOVER	0.00	0.00	*310.00 F	X
46	1		*FRT PARKING SENSOR LH	0.00	0.00	*260.00 F	✓
47	1		*CONDENSER	0.00	0.00	*1,085.00 F	X

48	1	*RADIATOR	0.00	0.00	h	*720.00 F	X
49	1	*CHARGE INTERCOOLER	0.00	0.00	h	*690.00 F	X
50	1	*FAN BLOWER ASSY	h	0.00	0.00	*1,600.00 F	X
51	1	*RADIATOR TOP COVER	h	0.00	0.00	*100.00 F	X
52	1	*COOLANT	h	0.00	0.00	*150.00 F	X

F=Franchise part.

Sub Total (S\$)	21,407.00
+ Margin on L,N Items 10.00% (S\$)	2,140.70
Total Parts (S\$)	23,547.70

Convergence Automotive Pte Ltd/SNJ1278R/12/06/2024 17:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS



Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAY PAINT	New	880.00
<u>Labour Items</u>			
2	REPAIR WORK	New	2,240.00
3	WIRING + CODING	New	1,500.00
4	TOP UP COOLANT + GAS	New	150.00
Gross Labour Cost (\$\$)			4,770.00

6001

6001

201

X

Convergence Automotive Pte Ltd/SNJ1278R/12/06/2024 17:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: