

INSURER: ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC24P00082100	Date of Loss:	11/06/2024
Vehicle Reg. No.:	SNJ1278R	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ZHU QIURONG		
Make/Model:	BMW 528i, 2.0 D/AB 2WD 4DR GAS/D NAV (A)	Vehicle Reg. Date:	25/03/2013
Vehicle Colour:	White		
Engine No:	A0120424N20B20A	Chassis No:	WBAXG32050D12183
Odometer:	252151 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5 days		
Present Location:	CONVERGENCE AUTOMOTIVE PTE LTD (HQ)		

NOT NOTION

Repair B & paint
Ex 8350h

11/06/2024 86550h

COST OF CLAIMS	Amount
Parts	23,547.70
Miscellaneous Items	0.00
Labour	3,890.00
Paintwork Labour	880.00
Towing	0.00
Calculated Gross Total (S\$)	28,317.70
- Excess (S\$)	600.00
(S\$)	27,717.70
+ GST 9.00% (S\$)	2,494.59
Nett Amount (S\$)	30,212.29

This claim is handled by: WONG SIANG YEE

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jun 2024)
Parts: 143 BMW 528i 2.0 D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Convergence Automotive Pte Ltd/SNJ1278R/12/06/2024 17:25
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BONNET 1500	0.00	0.00	*2,500.00 F	✓
2	1		*BONNET HINGE LH	0.00	0.00	*175.00 F	X
3	1		*BONNET HINGE RH	0.00	0.00	*175.00 F	X
4	2		*BONNET GAS ABSORBER	0.00	0.00	*270.00 F	X
5	1		*BONNET SEAL FRT	0.00	0.00	*65.00 F	X
6	1		*BONNET SEAL REAR	0.00	0.00	*85.00 F	X
7	1		*ENGINE UPPER SEAL COVER LH	0.00	0.00	*235.00 F	X
8	3		*BONNET STOP BUFFER	0.00	0.00	*30.00 F	X
9	2		*BONNET ADJUSTER	0.00	0.00	*36.00 F	X
10	1		*BONNET BONNET LOWER LOCK LH (W/ELEC) 120	0.00	0.00	*280.00 F	✓
11	1		*BONNET LOWER LOCK RH	0.00	0.00	*255.00 F	X
12	1		*BONNET UPPER LOCK LH	0.00	0.00	*115.00 F	X
13	1		*BONNET UPPER LOCK RH	0.00	0.00	*115.00 F	X
14	1		*BONNET LOCK CABLE (4)	0.00	0.00	*65.00 F	X
15	1		*FRT FENDER LH	0.00	0.00	*780.00 F	X
16	1		*FRT FENDER BRACKET (2)	0.00	0.00	*40.00 F	X
17	1		*FRT FENDER SPACER LH	0.00	0.00	*42.00 F	X
18	1		*FRT FENDER INNER SHIELD LH	0.00	0.00	*195.00 F	X
19	1		*HEADLAMP LH	0.00	0.00	*2,350.00 F	✓
20	1		*HEADLAMP LED MODULE LH (2)	0.00	0.00	*580.00 F	X
21	1		*HEADLAMP INDICATOR INSERT LH (6)	0.00	0.00	*425.00 F	X
22	1		*HEADLAMP CONTROL UNIT LH	0.00	0.00	*1,050.00 F	X
23	1		*HEADLAMP DRIVE AHL MODULE LH	0.00	0.00	*990.00 F	X
24	1		*SUPPORT HEADLAMP LWR BRACKET LH	0.00	0.00	*290.00 F	X
25	1		*SUPPORT V-STRUT BAR LH	0.00	0.00	*55.00 F	X
26	1		*SUPPORT V-STRUT BAR RH	0.00	0.00	*55.00 F	X
27	1		*SUPPORT PANEL CONNECTION FRT 420	0.00	0.00	*550.00 F	✓
28	1		*SUPPORT PANEL CONNECTION REAR	0.00	0.00	*420.00 F	X
29	1		*SUPPORT AIR DUCT	0.00	0.00	*790.00 F	X
30	1		*FRT BUMPER ORIGINAL	0.00	0.00	*1,350.00 F	✓
31	1		*FRT BUMPER HOLDER LH	0.00	0.00	*14.00 F	✓
32	1		*FRT BUMPER WASHER CAP LH	0.00	0.00	*48.00 F	✓
33	1		*FRT BUMPER WASHER CAP LEVER LH	0.00	0.00	*22.00 F	X
34	1		*FRT BUMPER WASHER CAP SPRING LH	0.00	0.00	*9.00 F	X
35	1		*FRT BUMPER WASHER CAP PLUG LH	0.00	0.00	*16.00 F	X
36	1		*FRT BUMPER LWR CTR GRILLE	0.00	0.00	*125.00 F	X
37	1		*FRT BUMPER LWR SIDE GRILLE LH	0.00	0.00	*110.00 F	X
38	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*790.00 F	X
39	1		*FRT BUMPER IMPACT ABSORBER	0.00	0.00	*150.00 F	X
40	1		*FRT BUMPER LOWER BEAM	0.00	0.00	*180.00 F	X
41	1		*FRT BUMPER LOWER BEAM BRACKET LH	0.00	0.00	*130.00 F	X
42	1		*FRT GRILLE LH	0.00	0.00	*220.00 F	✓
43	1		*FRT GRILLE RH	0.00	0.00	*220.00 F	X
44	1		*FRT LOGO	0.00	0.00	*95.00 F	✓
45	1		*FRT BUMPER UNDERCOVER	0.00	0.00	*310.00 F	X
46	1		*FRT PARKING SENSOR LH	0.00	0.00	*260.00 F	✓
47	1		*CONDENSER	0.00	0.00	*1,085.00 F	X


48	1	*RADIATOR	0.00	0.00	h	*720.00 F	X
49	1	*CHARGE INTERCOOLER	0.00	0.00	h	*690.00 F	X
50	1	*FAN BLOWER ASSY	0.00	0.00	h	*1,600.00 F	X
51	1	*RADIATOR TOP COVER	0.00	0.00	h	*100.00 F	X
52	1	*COOLANT	0.00	0.00	h	*150.00 F	X

F=Franchise part.

Sub Total (\$\$)	21,407.00
+ Margin on L,N Items 10.00% (\$\$)	2,140.70

Total Parts (\$\$)	23,547.70
--------------------	-----------

Convergence Automotive Pte Ltd/SNJ1278R/12/06/2024 17:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS



Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAY PAINT	New	880.00
<u>Labour Items</u>			
2	REPAIR WORK	New	2,240.00
3	WIRING + CODING	New	1,500.00
4	TOP UP COOLANT + GAS	New	150.00
Gross Labour Cost (S\$)			4,770.00

6001
6001
201
X

Convergence Automotive Pte Ltd/SNJ1278R/12/06/2024 17:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: