

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 29.07.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNJ745R**
MODEL : **KIA CARENS**
DATE OF ACCIDENT : 23.07.2024
TIME OF ACCIDENT : 12:25 HOURS

Xiao Chan

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER (UPPER) <i>3 Deformed</i>	1	\$ 598.00	\$ 598.00
2	REAR BUMPER (LOWER)	1	\$ 387.00	\$ 387.00
3	REAR BUMPER DIFFUSER <i>Deformed</i>	1	\$ 288.00	\$ 288.00
4	REAR BUMPER LAMP LH <i>Cracked</i>	1	\$ 116.00	\$ 116.00
5	REAR BUMPER SIDE INNER GARNISH LH <i>new</i>	1	\$ 153.00	\$ 153.00
6	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 20.00	\$ 20.00
7	REAR BUMPER SENSOR <i>1 piece deformed</i>	2	\$ 187.00	\$ 374.00
8	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 36.00	\$ 144.00
9	REAR BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 348.00	\$ 348.00
10	REAR BUMPER BRACKET <i>new</i>	5	\$ 21.00	\$ 105.00
11	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 39.00	\$ 78.00
12	REAR BUMPER REINFORCEMENT <i>Cracked</i>	1	\$ 428.00	\$ 428.00
13	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 152.00	\$ 304.00
14	TAILGATE <i>Deformed</i>	1	\$ 1,088.00	\$ 1,088.00
15	TAILGATE OUTER GARNISH <i>Cracked</i>	1	\$ 486.50	\$ 486.50
16	TAILGATE LAMP <i>LH Cracked</i>	2	\$ 243.00	\$ 486.00
17	TAILGATE LOGO <i>2 new</i>	1	\$ 76.00	\$ 76.00
18	TAILGATE EMBLEM 'CARENS'	1	\$ 64.00	\$ 64.00
19	TAILGATE EMBLEM 'TURBO'	1	\$ 59.00	\$ 59.00
20	TAILGATE DETECTOR <i>new</i>	1	\$ 346.00	\$ 346.00
21	TAILGATE DETECTOR WIRE HARNESS <i>new</i>	1	\$ 259.00	\$ 259.00

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNJ745R**
 MODEL : **KIA CARENS**
 DATE OF ACCIDENT : 23.07.2024
 TIME OF ACCIDENT : 12:25 HOURS

22	TAILGATE STOPPER <i>new</i>	2	\$ 14.00	\$ 28.00	+
23	TAILGATE LOCK CATCH <i>new</i>	1	\$ 19.00	\$ 19.00	+
24	TAILGATE WEATHER STRIP <i>lt</i>	1	\$ 168.00	\$ 168.00	✓
25	TAILLAMP <i>LHA angled</i>	2	\$ 397.00	\$ 794.00	397
26	REAR FENDER INNER COWLING <i>2x4x5 in</i>	2	\$ 224.00	\$ 448.00	+
27	REAR FENDER INNER TRIM <i>for angled LHA</i>	2	\$ 474.00	\$ 948.00	+ 474
28	REAR END PANEL <i>Rebuilt</i>	1	\$ 594.00	\$ 594.00	—
29	REAR END PANEL TOP GARNISH <i>angled</i>	1	\$ 127.00	\$ 127.00	—
30	REAR STORAGE BOX <i>angled</i>	1	\$ 386.00	\$ 386.00	—

6310.50
5679.45

TOTAL PRICE \$ 9,719.50
 LESS 10% \$ 971.95
 SUB TOTAL PRICE \$ 8,747.55

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER (UPPER) CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
2	REAR BUMPER (LOWER) CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
4	TAILGATE INNER TRIM REFLECTOR <i>new</i>	2	\$ 20.00	\$ 40.00	+
5	TAILGATE INNER TRIM CLIP <i>new</i>	1	\$ 50.00	\$ 50.00	30+
6	TAILGATE WINDSCREEN SEALANT <i>2 new</i>	1	\$ 80.00	\$ 80.00	40
7	TAILGATE WINDSCREEN INNER SHIELD	1	\$ 60.00	\$ 60.00	30
8	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
9	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
10	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
11	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
12	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	20

210

TOTAL \$940.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	700

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNJ745R**
 MODEL : **KIA CARENS**
 DATE OF ACCIDENT : 23.07.2024
 TIME OF ACCIDENT : 12:25 HOURS

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	600
3	TUFF COAT	\$ 350.00	60
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
6	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
7	CONDUCT WATER LEAKAGE TEST	\$ 250.00	+
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	+

TOTAL \$4,980.00

ESTIMATE REPORT

TOTAL PARTS COST : \$9,687.55
 TOTAL LABOUR COST : \$4,980.00
 TOTAL REPAIR COST : \$14,667.55

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian
 2/8 01/08/24
 06 Days

Total: 7539.45

L/S: 6K ✓

1650