

S.D CAR CARE CENTRE

Blk 2, Kaki Bukit Avenue 2, #01-29, (Kaki Bukit AutoHub), Singapore 417921

H/P: 9616 1359 (Ah Boon) / 9650 7403 (Ah Boy)

Tel: 6749 6155 / 6745 5102 / Fax: 6742 9003

not Authorized
for
work
6/8/24
1/5 # 5400
Alaph. H. H. H.
5 days

Vehicle number: SLM5032P

Vehicle Made & Model: SUBARU OUTBACK

Qty	List Items	Amount \$
1	Tailgate <i>DD/Buf</i>	1,560.90 ✓
1 set	Tailgate glass moulding <i>all</i>	121.60 ✓
1	Tailgate emblem "SUBARU" <i>all</i>	89.60 ✓
1	Tailgate emblem "OUTBACK" <i>all</i>	99.60 ✓
1	Tailgate emblem "AWD" <i>all</i>	89.60 ✓
2	Tailgate lamps - L/R @ 361.20 <i>all</i>	722.40 X
1	Tailgate outer garnish <i>all</i>	411.50 X
1	Tailgate inner lock <i>Daye</i>	581.90 ✓
1	Tailgate inner trim board <i>all</i>	460.20 X
1	Tailgate w/strip <i>twl</i>	211.60 ✓
2	Taillamps - L/R @ 481.60 <i>all</i>	963.20 X
1	Rear bumper <i>Dis</i>	<i>694.50</i> 865.90 ✓
1	Rear bumper top plate <i>all</i>	381.90 ✓
1	Rear bumper lower guard <i>Tora</i>	360.50 ✓
2	Rear bumper lamps - L/R @ 210.60 <i>N/sero 0/5an</i>	421.20 <i>1PC</i>
2	Rear bumper side holders - L/R @ 89.90 <i>all</i>	179.80 X
2	Rear bumper side retainers - L/R @ 91.50 <i>all</i>	183.00 X
1	Rear bumper reinforcement <i>Buf</i>	571.60 ✓
1	Rear bumper tow cover <i>SC</i>	41.20 X
1	Rear end panel <i>DD/Buf</i>	531.60 ✓
1	Rear end panel garnish <i>all</i>	191.80 X
1	Rear exhaust silencer <i>all</i>	865.00 X
2	Rear exhaust insulator <i>all</i>	161.20 X
1	Rear floor board <i>all</i>	460.20 X
1	Rear floor compartment panel <i>all</i>	761.90 X
2	Rear smart keyless antenna <i>all</i>	181.20 X
Sub-total		11,470.10
Less 20%		2,294.02
Total List		9,176.08

Vehicle number: SLM5032P

Vehicle Made & Model: SUBARU OUTBACK

Special Nett Items

1 set	Tailgate glass sealant	121	80.00	40
1 set	Tailgate glass foam tape	121	65.00	20
1 set	Rear bumper clip	121	50.00	30
1 set	Rear reverse sensor	Walfactor	280.00	200
1	Rear reverse camera	11	450.00	X
Total Special Nett			925.00	

Labour charges

To check rear electrical wiring	50.00	20
To respray undercoating	100.00	60
To remove, refix tailgate glass	180.00	120
To remove, refix rear front interior trims to assist repair	120.00	60
To remove, refix reverse sensor / camera	80.00	30
Transfer & reinstall tailgate components to new tailgate	150.00	50
To respray painting and etc	1,400.00	950
Panel beating, cut, weld remove & replacing above parts	1,500.00	800
Total Labour	3,580.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 13,681.08

2-5505-50
202
4404-40
290
2090
6784-4
203
5421

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: