



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 ATTN: IRENE TAY			Ref: CS/CTI24080003/Rqh3m4(N) Date: 13/01/2025 Code: CTI	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	YQ 7566C
	Policy No.	DMCVSNW00092922200	Coverage (\$)	0.00
	Claim No.	SNM24D204080	Excess (\$)	350.00
	Assign From	IRENE TAY	Assign Date	31/07/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150 5MT	c.c	2755
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	JHHAGV4680K002382	Colour	GREY
	Odometer	95636 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195R15C	ARIVO	5 mm
	L/H Front Tyre	195R15C	ARIVO	3 mm
	R/H Rear Tyre	155R13C (D)	ARIVO	5/5 mm
	L/H Rear Tyre	155R13C (D)	ARIVO	5/5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/07/2024	Inspection Date	01/08/2024
	Survey held at	48 TOH GUAN ROAD EAST, ENT HUB, #02-143 (S) 608586		
	Repairer	AUTOMOTIVE REPAIR CENTRE PTE LTD		
5a. Remarks				
	A)THE MARKET VALUE IS S\$97,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	