

Date: 31/7/2024

Vehicle No: SBT12L

Model: TESLA MODEL 3

Chassis: LRW3F7EL7MC282999

Reg.Year: 2021

Third Party Insurer: AIG

Third Party Veh No: SLU8889Y

Date of Accident: 27/7/2024

Estimator: JONATHAN

Surveyor:

83479.19 *Estimate*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RR BUMPER			\$ <i>Per 120</i> 766.00 ✓
	RR BUMPER LHS RELFECTOR			\$ <i>CM</i> 20.56 ✓
	RR REINFORCEMENT BAR			\$ <i>R</i> 271.02 X
	RR BOOT			\$ <i>B</i> 728.97 ✓
	RR BOOT EMBLEM (LOGO)			\$ <i>NA</i> 37.38 —
	RR BOOT EMLBEM (DUAL MOTOR)			\$ <i>NA</i> 29.90 —
SUB TOTAL				\$ 1,853.83
Less 10%				-\$ 185.38
PARTS TOTAL				\$ 1,668.45

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	RR BUMPER CLIPS			\$ <i>NA</i> 50.00 ✓
	CAR WRAP		(Bill)	\$ 850.00 800/
S/N TOTAL				\$ 900.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix RR affected areas	\$	800.00	400/
To perform wiring checks on electrical systems	\$	30.00	20/
To remove, putty, repair, sand and respray affected areas	\$	600.00	400/
To remove, replace & refix bumper sensors	\$	30.00	✓
To remove, replace & reinstall Bootlid inner mechansim	\$	30.00	✓
To perform Adas Checks, Calibration & Programming	\$	200.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

LABOUR TOTAL	\$	1,690.00
TOTAL	\$	4,258.45

JONATHAN

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 3993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011



Date: 11/9/2024
Vehicle No: SBT12L
Model: TESLA MODEL 3
Chassis: LRW3F7EL7MC282999
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SLU8889Y
Date of Accident: 27/7/2024

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RR LOWER BUMPER - CUT			CM \$140.18
	RR BUMPER UNDERCOVER - DEFORMED			DTI \$205.60
	RR BUMPER HITCH COVER - MISSING			HIJ \$14.95
SUB TOTAL				\$360.73
LESS 10%				-\$36.07
PARTS TOTAL				\$324.66

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
S/N TOTAL				\$0.00

SUPPLEMENTARY

LABOUR CHARGES:

LABOUR TOTAL		\$0.00
VIC / TING AN	TOTAL	\$324.66

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1063

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-06 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

